




N

- ◀ Wind Direction Indicators (wind sock or streamers)
- △ H2S Monitors (alarms at bell nipple and shale shaker)
- Briefing Areas
- Remote BOP Closing Unit
- Sign and Condition Flags

EXHIBIT "D"
RIG LAY OUT PLAT

GREAT WESTERN DRILLING COMPANY
OUAIL FEDERAL # 10
UNIT "H" SECTION 23
T6S-R25E CHAVES CO. NM