

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
L-5070

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry well	7. Unit Agreement Name
2. Name of Operator McClellan Oil Corporation ✓	8. Farm or Lease Name Boldernhel
3. Address of Operator Post Office Drawer 730, Roswell, New Mexico 88201	9. Well No. 1
4. Location of Well UNIT LETTER D, 660 FEET FROM THE North LINE AND 660 FEET FROM THE West LINE, SECTION 36 TOWNSHIP 3-S RANGE 26-E NMPM.	10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 3805' G.L.	12. County De Baca

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugged well in following manner:

1/20/81: Spotted 20 sacks Class C plug from 4090' to 4240'.
Pulled 3,694 feet of 4½" casing.

1/21/81: Spotted 35 sack plug from 3650' to 3745'.
Spotted 35 sack plug from 1900' to 2000'.
Spotted 45 sack plug from 1150' to 1250': waited 2 hours and tagged cement at 1101'.
Spotted 10 sack plug at surface and installed dry hole marker.

Note: Will break pits after they are dry.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED <u>Paul Raysdale</u>	TITLE <u>Engineer</u>	DATE <u>1/27/81</u>
APPROVED BY <u>Miss Stupfield</u>	TITLE <u>OIL AND GAS INSPECTOR</u>	DATE <u>NOV - 4 1981</u>
CONDITIONS OF APPROVAL, IF ANY:		