

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

RECEIVED
NEW MEXICO OIL CONSERVATION COMMISSION
OCT 14 '87
O. C. D.
ARTESIA OFFICE

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

OCT 09 '87

5a. Indicate Type of Lease State ☒ Fee ☐
5. State Oil & Gas Lease No. LG-747
7. Unit Agreement Name
8. Farm or Lease Name State 17
9. Well No. 1
10. Field and Pool, or Wildcat Wildcat (San Andres)
12. County DeBaca

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL ☐ GAS ☒ OTHER ☐

2. Name of Operator
Flag-Redfern Oil Company

3. Address of Operator
P. O. Box 11050 Midland, TX 79702

4. Location of Well
UNIT LETTER P 660 FEET FROM THE South LINE AND 660 FEET FROM THE East LINE, SECTION 17 TOWNSHIP 1-S RANGE 25-E N41PM.

15. Elevation (Show whether DF, RT, GR, etc.)
4011.7 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

See attached procedure

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Kelly Jim TITLE Engineer DATE 10-7-87

APPROVED BY Mike Williams TITLE OIL AND GAS INSPECTOR DATE OCT 21 1987

CONDITIONS OF APPROVAL, IF ANY:

October 7, 1987

STATE "17" NO. 1

Procedure to Plug and Abandon

1. MIRU completion unit.
2. Pump down tubing and load hole with 10# brine (50 bbls.).
3. NU BOP. TOH with 2-3/8" tubing.
4. RU wireline. Set CIBP at 800'.
5. TIH 2-3/8" tubing to 800'. RU Halliburton. Circulate hole with mud laden fluid (9.5 lb./gal and 35 Vis).
6. Spot 35 sx Class "C" from 800' to 671'. POH laying down to 440'.
7. Spot 35 sx Class "C" from 440' to 311' (13-3/8" casing shoe).
8. TOH laying down 2-3/8" tubing.
9. Spot 10 sx Class "C" from 30' to surface.
10. Cut casing off. Weld on plate. Install a marker monument. Monument to be a minimum of 4" in diameter and extend 4' above ground level. To include following information:
 - A. Flag-Redfern Oil Company
State "17" No. 1
Unit Letter P, Sec. 17, T-1-S, R-25-E
11. Clean location as required.

STATE "17" NO. 1

10-6-87

Location: Sec. 17 T-1-S R-25-E
660' FSL and 660' FEL
DeWitt County, Texas

