

RECEIVED BY

DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Artesia, NM 88210

MAY 07 1984

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. O. C. D.

ARTESIA OFFICE

OTHER

P&A

2. NAME OF OPERATOR

Yates Petroleum Corporation

3. ADDRESS OF OPERATOR

207 South 4th St., Artesia, NM 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below.)

At surface

1980 FNL & 660 FWL, Sec. 26-T1N-R26E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3960.4' GR

5. LEASE DESIGNATION AND SERIAL NO.

NM 19988

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Kidd "ZF" Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat - Proba

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Unit E, Sec. 26-T1N-R26E

12. COUNTY OR PARISH

DeBaca

13. STATE

NM

16

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☐
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐
☐

REPAIRING WELL

☐
☐
☐
☒

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

Verbal permission obtained from Peter Chester, BLM, Roswell, NM, 5-1-84 to
plug and abandon well as follows:

TD 5962'. Release packer. TOOH. Lay down packer and TIH with tubing to
1300'. Pumped 25 sacks Class "C" and 35' cement plug. POOH to 1250'. Set
cement plug from 900-1250' w/40 sacks Class "C". POOH. WOC 2 hours. WIH
and tag cement plug at 880'. POOH to 60'. Pump 10 sacks Class "C" cement
to surface.

Install dry hole marker. Location will be cleaned and restored as per
BLM requirements.

I hereby certify that the foregoing is true and correct

SIGNED

TITLE Production Supervisor

DATE 5-3-84

(This space for Federal or State office use)

APPROVED BY

TITLE

APPROVED
PETER W. CHESTER

MAY 3 1985

*See Instructions on Reverse Side

BUREAU OF LAND MANAGEMENT
ROSWELL RESOURCE AREA