

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office New Mexico

Unit RECEIVED

JUM 3 6 1960

SUNDRY NOTICES AND REPORTS ON WELLS: C. C.

NOTICE OF INTENTION TO DRILL					
Office of mitterion to proper		SUBSEQUENT	REPORT OF WATER SH	UT-OFF	
OTICE OF INTENTION TO CHANGE PLAN		SUBSEQUENT	REPORT OF SHOOTING	OR ACIDIZING	
TICE OF INTENTION TO TEST WATER			REPORT OF ALTERING	CASING	
TICE OF INTENTION TO RE-DRILL OR				NG OR REPAIR	1 .
TICE OF INTENTION TO SHOOT OR AC		1 11		MENT	
TICE OF INTENTION TO SHOOT ON ACT		i li			
OTICE OF INTENTION TO ABANDON WE		Y			
TICE OF INTENTION TO ABANDON IN					
(INDICATE	ABOVE BY CHECK MA	ARK NATURE OF REPOR	T, NOTICE, OR OTHER D.	ATA)	
			June 7		, 19. 6 0
Murray	660 ft. fro	$\sum_{N=1}^{N}$ line and	1980 ft. fron		23
WV/A Sec. 23	3-8	2 4-E	nnpx		
NV/4 Sec. 23 (½ Sec. and Sec. No.)	(Twp.)	(Range)	(Meridian)		
	DeBaca		N	New Mexico	
Lldcat Desaca (Field) (County or Subdivision			(State or Territory)	
	ing points, and	all other important pr	oposed work)		
al Depth - 5372†	ing posites, and				
al Depth - 5372'	ing posites, and				
al Depth - 5372' bal approval obtaindon as follows: 50' plug from 4220	ned 6/6/6	O from Mr.	Carl Trays	ick to plug	
bal approval obtainden as follows: 50' plug from 4226 50' plug from 2800	ned 6/6/6 to 4270' to 2850'	O from Mr.	Carl Trays	ick to plug	8
al Depth - 5372' bal approval obtainden as follows: 50' plug from 4220 50' plug from 2800 50' plug from 1478	ned 6/6/6 to 4270' to 2850' to 1525'	O from Mr. (in & out	Carl Trays of 7-5/8*	ick to plug casing) that well	8
bal approval obtained as follows: 50' plug from 4226 50' plug from 2800 50' plug from 1475 Place a threaded of	ned 6/6/6 to 4270' to 2850' to 1525' sever on telegraphs	(in & out	Carl Trays of 7-5/8" ace pipe so to water we	ick to plug casing) that well	8
50' plug from 4226 50' plug from 2800 50' plug from 1475 Place a threaded of memoratered by rame	ned 6/6/6 to 4270' to 2850' to 1525' sever on telegraphs	(in & out	Carl Trays of 7-5/8" ace pipe so to water we	ick to plug casing) that well	8
bal approval obtainden as follows: 50' plug from 4220 50' plug from 2800 50' plug from 1478	ned 6/6/6 to 4270' to 2850' to 1525' sever on telegraphs	(in & out	Carl Trays of 7-5/8" ace pipe so to water we	ick to plug casing) that well	8
al Depth - 5372' bal approval obtained as follows: 50' plug from 4226 50' plug from 2806 50' plug from 1478 Place a threaded or re-entered by rand Set marker near wo	ned 6/6/6 to 4270 to 2850 to 1525 ever on teler for coll site a	(in & out top of surficencersion and clean up	of 7-5/8* ace pipe so to water we p location.	casing) that well	e may l
al Depth - 5372' al approval obtained as follows: 50' plug from 4226 50' plug from 2800 50' plug from 1475 Place a threaded of	ned 6/6/6 to 4270 to 2850 to 1525 ever on teler for coll site a	(in & out top of surficencersion and clean up	of 7-5/8* ace pipe so to water we p location.	casing) that well	e may l
al Bepth - 5372' bal approval obtained as follows: 50' plug from 4226 50' plug from 2806 50' plug from 1478 Place a threaded or re-entered by rand Set marker near wo	to 4270' to 2850' to 1525' sever on teler for coll site a	(in & out top of surficencersion and clean up	of 7-5/8* ace pipe so to water we p location.	casing) that well	e may l
al Depth - 5372' bal approval obtained as follows: 50' plug from 4226 50' plug from 2800 50' plug from 1478 Place a threaded of re-entered by rand Set marker near works I understand that this plan of works ompany Nearburg	to 4270° to 2850° to 1525° sever on the fer contact after a	(in & out top of surficencersion and clean up	of 7-5/8* ace pipe so to water we p location.	casing) that well	e may l
bal approval obtained as follows: 50' plug from 4226 50' plug from 2806 50' plug from 1478 Place a threaded of re-entered by rand Set marker near woods I understand that this plan of work to make the set of the set	to 4270° to 2850° to 1525° sever on the fer contact after a	(in & out top of surficencersion and clean up	of 7-5/8* ace pipe so to water we p location.	casing) that well coperations may be com	may i
al Depth - 5372' bal approval obtained as follows: 50' plug from 4220 50' plug from 2800 50' plug from 1478 Place a threaded or re-entered by rand Set marker near wo	to 4270° to 2850° to 1525° sever on the fer contact after a	(in & out top of surficencersion and clean up	of 7-5/8" ace pipe so to water we p location.	casing) that well coperations may be com	may i
al Depth - 5372' bal approval obtained as follows: 50' plug from 4226 50' plug from 2806 50' plug from 1475 Place a threaded of re-entered by rand Set marker near works ompany Nearburg 5 ddress P. O. Bex	to 4270' to 2850' to 1525' sever on teler fer coll site a	(in & out top of surficencesion and clean upon the	of 7-5/8" ace pipe so to water we p location.	casing) that well coperations may be com	may i
al Depth - 5372' bal approval obtained as follows: 50' plug from 4226 50' plug from 2806 50' plug from 1475 Place a threaded of the entered by rand Set marker near wo	to 4270' to 2850' to 1525' sever on teler fer coll site a	(in & out top of surficencesion and clean upon the	of 7-5/8* ace pipe so to water we p location.	casing) that well	may l

ILLEGIBLE

Rearburg & Ingram No. 1 Murray - Unit C of Section 23-35-

- 1. Pan American Petroleum Corp.
- 2. Pan American Petroleum Corp. 1/2 @ Nearburg & Ingram
- 3. Phillips Petroleum Company
- 4. Nearburg & Ingram

All offset operators have been notified as to our plugging