	3 mars	
NO. OF COPIES RECEIVED		Form C-103
DISTRIBUTION		Supersedes Old
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
FILE , —	RECEIVER	
U.S.G.S.		5a. Indicate Type of Lease
LAND OFFICE	AUG 1 1 1969	State Fee.
OPERATOR /	NOG 1 1 1000	5. State Oil & Gas Lease No.
		mmmmmmk
USE "APPLICAT	PY NOTICES AND REPORTS ON WELLS TERM & DEFUGE TO POSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DEFERM & DEFUGE TON FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)	
1. OIL GAS WELL WELL	OTHER-	7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
Bryce Duggar		Edna Gallagher
3. Address of Operator		9. Well No.
Box T56, Carris	Z0Z0, N.M.	10. Field and Pool, or Wildcat
UNIT LETTER	30 FEET FROM THE WAST LINE AND 330 FEET FRO	Wildcat
O anadria	26	
THE LINE, SECTION	ON 26 TOWNSHIP 6 RANGE TOE NMPN	
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
		Lincoln ()
Check	Appropriate Box To Indicate Nature of Notice, Report or O	ther Data
	· · · · · · · · · · · · · · · · · · ·	IT REPORT OF:
 7	. 55	
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	
	OTHER	
OTHER		
17. Describe Proposed or Completed Or	perations (Clearly state all pertinent details, and give pertinent dates, includin	g estimated date of starting any proposed
work) SEE RULE 1 103. This Well dri	lled to PD2I49, 1750 ft.to the SanA.	
	consisted of shales and lime shells	
The caving nature of the shales prevented all of the easing in		
these shaly formations from being pulled		
	MANAXAMANAXAMXAMA	
Wire basket se	et at 1850 I cubic foot of gravel dumped	on same
followed by IO bags commit this was permited to set five days		
while test was run on I595 foot section, swabed for 6 hours no show		
Friedto pull 5 casing failed set wire basket I620 dumped I cubic		
root gravel or	n same followed with IO bags cement dump	ped with dump
bailer. Knocked off collar 5 pipe at approximately IIOO feet		
set wire basket at bottom 5 pipe with I cubic foot gravel dumped		
IO bags sement, let set for 3 days bailed hole dry.		
Pulled all 5 appr. IIOO ft set wire basket at 850 ft dumped I subic foot gravel followed with IO bags cement.		
Tried to pull 735 ft 70d failed knocked off collar at appr.600 ft.		
Set wire basket at appr.650 ft dumped I cubic foot of gravel		
followed by 5 bags cement dumped with dump bailer.		
	et 70D pipe, pulled 50 fft 85/8 pipe ran 1	siler hole saved
	above is true and complete to the best of my knowledge and belief.	

GIL and the Attractor

DATE MAR 24 1971

and bridged, pulled 275 ft set were basket dumped I cubic foot gravel followed by IO bags cement. pulled IO joints 85/8 pipe ran bailer found hole bridged, pulled IA5 feet 85/8 pipe ran bailer found hole bridged at appr. 50 ft best eight bags down pipe dumped I5 bags cement around outside of 85/8 pape filled cavity with shale from slushpit, set plus in 85/8 set marker.

17. Describe Proposed or Completed Operations (Clearly state all partinent datails, and sive partinent dates' including estimated date of starting any proposed.