

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TR. CATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-8848

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

None

7. UNIT AGREEMENT NAME

None

8. FARM OR LEASE NAME

Federal (USA) "D"

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Undesignated

11. SEC., T., R., W., OR S.W. AND
SURVEY OR AREA

Sec. 29 T-7-S, R-9E

12. COUNTY OR PARISH 13. STATE

Lincoln

N. M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. NAME OF OPERATOR TEXACO Inc.	3. ADDRESS OF OPERATOR P.O. Box 728, Hobbs, New Mexico 88240	4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Well is located 1980' from the North Line and 1980' from the East Line of Section 29, T-7-S, R-9-E, Unit letter G, Lincoln County, New Mexico.	14. PERMIT NO. Regular	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 5412' (D.F.)
--	------------------------------------	---	---	---------------------------	--

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☐
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

☐
☐
☒
☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

THE FOLLOWING WORK HAS BEEN COMPLETED ON SUBJECT WELL:

1. Set Cement Plugs from:

5850' to 5750' w/40 Sx. cement.

4215' to 4115' w/40 Sx. cement.

3350' to 3250' w/40 Sx. cement.

1550' to 1450' w/40 Sx. cement.

2. Set 10 Sx. cement plug @ surface.

3. Install 4" marker extending 4' above ground level and clean location for inspection.

4. Well plugged abandoned 6-8-69.

RECEIVED
JUN 20 1969
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Assistant District
Superintendent

DATE

June 18, 1969

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

APR 25 1972

CONDITIONS OF APPROVAL, IF ANY: