

Larry -
 Nelson Muncy wants
 you to call him
 about plugging the
 Chisum YH #1
 24-2-19

Needs a plugging
 procedure

13 3/8 @ 443'

PBTD 4059
 3921

5 1/2

(TBC)

3504 - 3500
 3498 - 88 - 84
 80 (3940) 38 3/2
 10 1/2 2630-28-26
 24-22

443'

70 @

perfs 3875 - 74 - 73 - 72 - 63
 10 holes (38k) 15 1/2 - 15 - 14 1/2 - 14
 3764 - 3763 1/2 - 63 - 62 1/2 - 62
 12 3731 3730 3729 - 28 1/2 28

8 ⁵/₈
@ 1496'

10h.

3330, 3328, 26, 24 - 22

10 2780 2779 78 1176 50 49
h. 48 47 (46)

TOC 1850

CIBP @ 2700' w/ 100' cmt.
perf @ TOC, 100' out, 100' in
tag.

2330 - ~~24~~30 35 sxs.

794 - 694 G10.

500 - 400 \$ tag perf
Run 1jt & circ in/out