

**SUNDRY NOTICES AND REPORTS ON WELLS**  
Use APPLICATION FOR PERMIT for such proposals.)

1. OIL WELL ☒ WATER WELL ☐ OTHER P&A

2. NAME OF OPERATOR  
Yates Petroleum Corporation

3. ADDRESS OF OPERATOR  
207 South 4th St., Artesia, NM 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface  
1780 FNL & 1980 FEL, Sec. 25-T4S-R14E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)  
6014' GR

5. LEASE DESIGNATION AND SERIAL NO.  
NM 37955

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME  
Boggle "ZH" Federal

9. WELL NO.  
1

10. FIELD AND POOL, OR WILDCAT  
Wildcat Precambrian

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
Unit G, Sec. 25-4S-14E

12. COUNTY OR PARISH  
Lincoln

13. STATE  
NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	(Other) <input type="checkbox"/>


(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

12-4-84. TD 2662'. Plugged and abandoned well as follows:

Set CIBP at 2000' w/35' cement on top.  
Cut 4½" casing at 900' and pull.  
Spot 150 sx Class "C" cement plug from 948-628'.  
Spot 15 sx cement plug at surface.  
Install dry hole marker.  
Completed plugging 12-6-84.

Verbal permission obtained from Peter Chester, BLM, Roswell, for plugging.



Post ID-2  
1-25-85  
P+A

18. I hereby certify that the foregoing is true and correct

SIGNED Pamela Goodlett TITLE Production Supervisor DATE 12-7-84

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

APPROVED  
PETER W. CHESTER  
DATE  
MAY 3 1985  
BUREAU OF LAND MANAGEMENT  
ROSWELL RESOURCE AREA

\*See Instructions on Reverse Side