D 2160 . 5			rom approved. Budget Bureau No. 1004-0135
-	UNI D STATES ARTMEN: OF THE INTER! JREAU OF LAND MANAGEMENT	OPC Assected	Expires August 31, 1985 5. LEASE DESIGNATION AND SERIAL NO. NM 37451
SUNDRY I	NOTICES AND REPORTS C proposals to drill or to deepen or plug b PPLICATION FOR PERMIT—" for such pr	ON WELLS	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
OIL GAS OTHER P&A			7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR			8. FARM OR LEASE NAME
Yates Petroleum Corporation ✓		RECEIVED BY	Asparas ABX Federal 9. WALL NO.
207 South 4th St., Artesia, NM 88210 4. LOCATION OF WELL (Report location clearly and in accordance with any See also space 17 below.) At surface 790 FNL & 1980 FWL, Sec. 21-T4S-R161			1
		rrete seduceBental 1881	Wildcat - FIDO
		O. C. D. ARTESIA, OFFICE	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
14. PERMIT NO.	15. ELEVATIONS (Show whether DF		Unit C, Sec. 21-T4S-R16E
14. PERMIT NO.	5635' CR	, 111, 411, 642,	Lincoln NM
16. Chec	ck Appropriate Box To Indicate N	lature of Notice, Report, or	Other Data
NOTICE OF INTENTION TO:			EQUENT REPORT OF:
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT SHOOTING OR ACIDIZING	ALTERING CABING ABANDONMENT* X
REPAIR WELL	ABANDON* CHANGE PLANS	(Other)	
(Other)		Completion or Recor	lts of multiple completion on Well appletion Report and Log form.) tes, including estimated date of starting any
2-26-85 to plug Plug #1: 2380-2 Plug #2: 1880-1 Tagged Plug #3: 1580-1 Tagged Plug #4: 50'-Si	well as follows: 2280' 35 sacks Class "C" 1780' 40 sacks Class "C" 1 at 1800'. 1480' 50 sacks Class "C" 1 at 1500'. 1 at 1500'. 1 at 1500'.	Neat. PD 2:30 AM Neat w/4% CaC12. Neat w/4% CaC12. Neat. PD 7:00 AM	PD 3:15 AM 2-27-85.
18. I hereby certify that the fore	- C)		The state of the s
SIGNIFICANTE	Stadless TITLE I	Production Superviso	
(The space for Federal or Si	tate office use)	,	PETER W. CHESTER
APPROVED BY	L, IF ANY: Approved as to plugging of	of the well hore.	
	Liability under bond is ret	ained until	JAN 30 1987
And the second	surface restoration is con *See Instruction	ppleted <u>.</u> s on Rev erse Side	BUREAU OF LAND MANAGEMENT