N. M. O. C. C. COPY	Cof 1 ~~
TOTAL STATE OF TAKE	Form approved.
DEPARIMENT OF THE INTERIOR (Other Instr. one on-	
GEOLOGICAL SURVEY	NM 8831
CUNDRY MOTICES AND DEPONTS ON WELLS	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir	
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)	
1. OIL GAS C	7. UNIT AGREEMENT NAME
WELL WELL OTHER 2. NAME OF OPERATOR	
	8. FARM OR LEASE NAME
TEXACO Inc. 3. Address of Operator	Federal (USA) "F" NCT-
	9. WELL NO.
P. O. Box 728 - Hobbs, New Mexico 88240 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.	10. FIELD AND POOL, OR WILDCAT
See also space 17 below.) At surface	· · · · · · · · · · · · · · · · · · ·
1980' FSL and 1980' FEL, Sec 30, T-18-S, R-10-E	Wildcat 11. SEC., T., B., M., OR BLK. AND
1300 100 and 1300 100, Sec 30, 1-10-5, K-10-D	SURVEY OR AREA
	Sec 30, T-18-S, R-10-E
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
Regular 4043' GR	Otero New Mexico
Check Appropriate Box To Indicate Nature of Notice, Report, o	r Other Data
VA 02 01-11-11	and the second of the second o
	SEQUENT REPORT OF
TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT MULTIPLE COMPLETE FRACTURE TREATMENT	ALTERING CASING
SHOOT OR ACIDIZE ABANDON* SHOOTING OR ACIDIZING REPAIR WELL CHANGE PLANS (Other)	ABANDONMENT*
(Other) (Note: Report res	ults of multiple completion on Well
17 DESCRIBE PROPOSED OF COMPLETED OPERATIONS (Cloudy state all postions details	tes including estimated data of recently
proposed work. If well is directionally drilled, give subsurface locations and measured and true vel nent to this work.) *	rtical depths for all markers and zones perti-
The following work has been completed on subject well:	그는 원의 복취합위의 휴 정상에 된 됐다.
<pre>1. Set cement plugs from: 7650' to 7550' w/60 sx cement</pre>	
7100' to 7000' w/60 sx cement	
5950' to 5850' w/60 sx cement	
4100' to 4000' w/75 sx cement	Mr.
3400' to 3300' w/75 sx cement	
2500' to 2400' w/100 sx cement	n NOV
	\$ 60 9 70
Set 45 sx cement plug at surface.	ARTESIA SONO
3. Install 4" marker extending 4' above ground and clean loc	cation.
N 77-99 - 1 1 - 1 1	
4. Well plugged and abandoned.	그는 그 경원하는데 함께 취하고통
Notes Verbal compaging to also and shandon massigned 6.200	
Note: Verbal permission to plug and abandon received 6:30	Eur Culon 1 8% Tale
	APR 27 1972
	APR
18. I hereby certify that the foregoing by true and correct	
Assistant District	O. L. OFFICE
SIGNED TITLE Superintendent	ARTES November 5, 1970
(This space for Federal or State office are)	AND 0 P 4070
APPROVED BY TITLE DISTRICT ENGINEER	APR 2 5 1972
CONDITIONS OF APPROVAL, IF ANY:	DATE
	4 T S S S S S S S S S S S S S S S S S S