	. ;		•	υİ	
S	A S	C I	O U R	A R	Name Mike Williams Date79 Miles272District
2 R C	S X	L I	s	T E	Name <u>Mike Williams</u> Bate <u>9-17-79</u> Miles <u>175</u> District <u>175</u> Time of Departure <u>8:00 a.m.</u> Time of Return <u>4:30 p.m.</u> Car NoOF <u>4693</u>
r I	SARIC	т Т У		R	
о N	λ. Τ Ι	-		H O	In the space below indicate the purpose of the trip and the duties performed, listing wells or leases visited and any action taken.
	о N			U R	Signature Mine Williams
	1			S	
	0		-		
- 0	0	0	7	2	<u>1 Well</u> 12-12S-9E, W. J. Conover, J.M.Lelelling #1 Trip to check status of well.
	•				Checked well and found well not producing. The road has washed out to well. There are no lines
:					hooked up to well for sales or for producing.
					There are two blow down lines from well head to pit. The well is colsed in.
	ł				I visited with Mr. W. J. Conover and at the present
					time he is planning on selling the well. He will
}	t			-	notify us when he sells the well or before he produces the well.
			1		
1					
•					
			ĺ		
		•			
l					
i i		}			
					NUL FACE PER DIEM HOURS
	1			1	MILEAGE IER DIEN
	L	1	L.	4	UIC <u>272</u> UIC <u>8.00</u> UIC <u>712</u>
1	rr	X	u d		Non UIC 272 Non UIC 8.00 Non UIC 712
Ű.			·	CTIO	INSPECTION NATURE OF SPECIFIC WELL OR FACILITY INSPECTED
			FORMI		CLASSIFICATION = Dry inspec- D = Drilling
	p =	Plu	gging	oping J	tion of ar related to injection project, $I = Injection$
	T =	Wel.	l Tes	g Cle st	injection into any well. (SWD, Zhary inj. operations injection and production wells, water
•	F =	Wat	orflo	√orko ⊳w or Sp	flows or pressure tests, surface $U = Underground$
	3 =	- Mat - Wat - Oth	er Co	ontam	ination $O = O $ ther - Inspections not related to $G = G $ eneral
	U =	0	~1		E = Indicates some form of enforcement action 0 = Other
					taken in the field (show immediately