N :. OF COPIES RECEIVED	1			•	
DISTRIBUTION	·		Form C-103 Supersedes Old		
SANTA FE	NEW MEXICO OIL CONSERVEDIEN COMEISSING E D		C-102 and C-103		
FILE	HEW MEXICO OIL CONS	ER THI I COMMISSION E	Effective 1-1-	65	
U.S.G.S.		050 00000	Sa. Indicate Type	of Lease	
LAND OFFICE	SEP 2.8 1978		State X Fee		
OPERATOR		5. State Oil & Gas Lease No.			
D. C. C.					
SUNDRY NOTICES AND REPORTS ON WELLS					
(DO NOT USE THIS FORM FOR PROPOSALS TO ORILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)					
i. OIL [] GAS []			7. Unit Agreemen	t Name	
WELL WELL	отнея- Wildcat				
2. Name of Operator			1	8. Farm or Lease Name	
Terra Resources, Inc.			Burro Canyon Unit		
3. Address of Operator			1-Y		
200 Wall Towers West, Midland, TX 79701			10. Field and Pool, or Wildcat		
				Wildcat	
UNIT LETTER J . 2030 FEET FROM THE SOUTH LINE AND 2080 FEET FROM					
THE East LINE, SECTION 2 TOWNSHIP 21-S RANGE 20E NMPM.					
THE LAST LINE, SECTION 2 TOWNSHIP 21 B RANGE NMPM.					
15. Elevation (Show whether DF, RT, GR, etc.)			12. County	7111111	
5145' GR			Otero		
Check Appropriate Box To Indicate Nature of Notice, Report or Oth			her Data		
NOTICE OF INTENTION TO:   SUBSEQUENT REPORT OF:					
	1	·			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK			ALTER	ING CASING	
TEMPORARILY ABANDON	·	COMMENCE DRILLING OPNS.	PLUG A	IND ABANDONMENT	
PULL OF ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB			
		OTHER			
OTHER					
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed					
work) SEE RULE 1103.					
8-19-78 - RIH to 5500, Hole stayed full. Set 35 sks. class H, plug #1 from 5500' to 5400', p.o.h. to 4700, set 30 min, hole stayed full so plug stayed in place, mix slurry 15.9 & set plug #2 with 35 sacks class H 15.9 #1 gal from 4700 to 4600, p.o.h. to 2450, hole full, set plug #3 from 2450 to 2350 w/35 sks. class H 15.9 #/ gal, p.o.h. to 1640, hole stayed full, no sign of loss, set plug #4 from 1640 to 1540 w/35 sks. class H 15.9 #/ gal, finish laying down d.p. and nipple down B.O.P., set 10 sacks class H surface plug and cut Braden Head off, put dry hole marker on. SE/4 Sec. 2-T21S-R20E, Otero County, New Mexico TD 5588 Elv. 5145' ground level.					
4	above is true and complete to the best o	of my knowledge and belief.		18 P P P P	
SIGNED HOTHERE D. St.	acia Ar	ea Operations Engineer	9-	20-78	
APPROVED BY	71746		DATE		

CONDITIONS OF APPROVAL, IF ANYI