

NO. OF COPIES RECEIVED	
DISTRIBUTION	
ANTA FE	
FILE	
J.S.G.S.	
LAND OFFICE	
OPERATOR	

RECEIVED
NEW MEXICO OIL CONSERVATION COMMISSION

SEP 11 1980

O. C. D.
ARTESIA, OFFICE

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)		5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
		5. State Oil & Gas Lease No. N/A
OIL <input checked="" type="checkbox"/> GAS <input type="checkbox"/> OTHER- <u>NEW WELL</u>		7. Unit Agreement Name
Name of Operator PENNZOIL COMPANY		8. Farm or Lease Name Southland 32 State
Address of Operator P.O. Drawer 1828, Midland, Texas 79702		9. Well No. 1
Location of Well UNIT LETTER <u>P</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>32</u> TOWNSHIP <u>25-S</u> RANGE <u>18-E</u> NMPM.		10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 3993.6 GR		12. County Otero

6. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <u>Drill prod.hole & set 4½" csg.</u> <input checked="" type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8/3/80 thru 8/25/80 Drilled 7-7/8" hole to 3635'.
8/26/80 Ran logs (DIL, Density Neutron).
8/27/80 thru 8/28/80 Waiting on compressors.
8/29/80 Drilled to 3800'.
8/30/80 thru 9/1/80 Stuck at 4060. Backed off at 3769'. POOH & P.U. Jars. WIH but could not get back down to fish. Left 300' of drill collars in hole. POOH w/fishing tools.
9/2/80 Circulated hole w/air & water. Hole caved in up to 3600'. POOH w/collars & bit.
9/3/80 WIH w/bit and drill pipe. Spotted 25 BBLS mud w/20-25#/Bbl LCM. At 3450'. Began laying down drill pipe.
9/4/80 Finished L.D. drill pipe. Ran 83 Jts of 4½", 10.5#, K-55, 8 RD csg. Set pipe at 3443' and cmt w/200 sks 50/50 POZ w/5# gilsonite, 5# salt and ½# flocele per sk followed by 100 sks of class C w/5# gilsonite ½# flocele and 2% C.C. per sk. Plug down at 4:25 PM 9/4/80. Released rig at 12 midnight 9/4/80. Prep to complete.

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J. V. Dullin TITLE Operations Engineer DATE 9/5/80

APPROVED BY W. A. Gress TITLE SUPERVISOR, DISTRICT II DATE SEP 18 1980

CONDITIONS OF APPROVAL, IF ANY: