

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993
5. Lease Designation and Serial No.

CLSF

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well
☐ Oil Well ☐ Gas Well ☒ Other INJECTION

2. Name of Operator
TIPTON OIL & GAS ACQUISITIONS

2. Address
P.O. BOX 1234, LOVINGTON, NM 88260

3. Location of Well (Footage, Sec., T., R., M., or Survey Description)
Unit Letter J, Sec. 31, T14S, R30E

6. If Indian, Allottee or Tribe Name

7. If Unit or C.A. Agreement Designation

8910160560

8. Well Name and No.

Double L Queen Unit #002

9. API Well No.

30-005-20348

10. Field and Pool or Exploratory Area
Double L Queen Associated

11. County or Parish, State
Chaves, NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION	
☒ Notice of Intent	☒ Abandonment	☐ Change of Plans
☐ Subsequent Report	☐ Recompletion	☐ New Construction
☐ Final Abandonment Notice	☐ Plugging Back	☐ Non-Routine Fracturing
	☐ Casing Repair	☐ Water Shut-Off
	☐ Altering Casing	☐ Conversion to Injection
	☐ Other	☐ Dispose Water

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Intend to P&A this SI WIW, we will notify OCD and ~~BLM~~ 24hrs prior to start
MIRU, POOH w/tbg (4-1/2" csg @ 2040' w/250 sx, with Perfs @ 1974-1979
Set CIBP @ 1924' w/ 35' cement on top
RIH, circ well w/9.8 mud
POOH to 1350', spot 100' cmt plug *Perf. csg. @ 1250' square 100' of cmt inside & outside csg 1150' - 1250' - TA9*
POOH to 419', spot 100' cmt plug (8 5/8" @ 369 w/150 sx), WOC & tag *Perf. csg. @ 419' square 100' of cmt inside & outside csg 319-419 - TA9*
POOH to 319', circulate cmt to surface *Perf. csg. @ 60' - circ. cmt 0-60'*
Cut of WH, install dry hole marker

14. I hereby certify that the foregoing is true and correct

Signed *[Signature]* Title Agent

Date 2-19-02

(This space for Federal or State office use)

Approved by _____ Title _____
Consent of approval, if any: