

COPIES RECEIVED	5
DISTRIBUTION	
SANTA FE	/
FILE	/
J.S.G.S.	
LAND OFFICE	
OPERATOR	3

RECEIVED
NEW MEXICO OIL CONSERVATION COMMISSION

FEB 4 1970

O. C. C.
ARTESIA, OFFICE

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K-6798

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name -
2. Name of Operator Read & Stevens, Inc. ✓	8. Farm or Lease Name Trobough
3. Address of Operator P. O. Box 2126, Roswell, New Mexico 88201	9. Well No. 1
4. Location of Well CORNER LETTER J ⁰ , 1650 FEET FROM THE South LINE AND 1650 FEET FROM THE East LINE, SECTION 1 TOWNSHIP 15S RANGE 27E NMPM.	10. Field and Pool, or Whichever (Buffalo Valley - Per)
15. Elevation (Show whether DF, RT, GR, etc.) 3517.2' GL	12. County Chaves

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1108.

2-1-70: Ran 266 jts, 8576.49' of 4½", 11.6#, 10.5#, 9.5#, J-55, N-80, LT&C, ST&C csg, set @ 8575' RKB. Cmt w/350 sx Trinity Inferno w/3/4 of 1% CFRZ, w/8# salt per sx. 500 gal mud flush ahead of cmt. Csg equip w/20 scratchers & 10 centr on bottom, 10 jts.guide shoe & insert float collar. Plug down @ 2:50 AM 2-1-70. Press test to 1500# for 30 min. Test OK. WOC 18 hrs.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Agent DATE 2-3-70

APPROVED BY [Signature] TITLE OIL AND GAS INSPECTOR DATE FEB 4 1970
CONDITIONS OF APPROVAL, IF ANY: