

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

CISF
Op

Form C-103
Revised 10-1-77

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☐
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER-
2. Name of Operator Delmar W. Berry
3. Address of Operator P.O. Box 512 ALto, N.M. 88312
4. Location of Well
UNIT LETTER K 1980 FEET FROM THE SOUTH LINE AND 1980 FEET FROM
THE West LINE, SECTION 2 TOWNSHIP 15 RANGE 29 N.M.P.M.
10. Field and Pool, or Wildcat Double L Queen
11. Elevation (Show whether DF, RT, GR, etc.) 3866 GR
12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
FULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Spot 25 SKS @ 1900'-1800' TAG
2. Spot 20 SKS @ 850'-650'. Perforate 4 1/2" csg @ 850'. Squeeze 100' cat Plug inside + Outside 4 1/2" csg. TAG
3. Perforate @ 250' - Sg2. 55 SKS - leave casing Full.
Circulate cement to surface inside + outside, 4 1/2" csg from 250'.
Cir. 9.5# mud
Install Dry Hole Marker

+ Notice N.M.O.C.D. to witness Plugging Operations

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Agent DATE 2-16-01

APPROVED BY [Signature] TITLE Field Rep II DATE 3/8/2001

CONDITIONS OF APPROVAL, IF ANY: