

Form 1-91
(May 1962)

STRICTLY IN TRIPPLICATE
(Refer Instructions on Reverse Side)

Form Approved
Budget Bureau No. 43-21424
GSA FPMR (41 CFR) Part 101-11.2

AMERICAN OFFICE COPY
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

104-16114
FEDERAL ELECTION IN TEXAS PARK

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir
use "APPLICATION FOR PERMIT" for such proposals.)

OIL WELL GAS WELL OTHER

2. NAME OF OPERATOR

WOOD & COOMBER, INC.

3. ADDRESS OF OPERATOR

511 West Ohio, Midland, Texas 79701

4. LOCATIONS OF WELL: Report locations clearly and accurately with any State requirements.
See also question 1 below.
All sections

Unit letter P Located 560' from the East line and
510' from the South line of Section 3.

14. PERIOD TO

15. DRILLING AND OTHER OPERATIONS (See Question 16, 17, 18, 19)

3852' GL

CITY OR MUNICIPALITY

Federal Park

SECTION OR TOWNSHIP

Double L, Queen Assoc.
T-15 S., R-29 E.

Sec. 3, T-15 S., R-29 E.

16. PERIOD OF DRILLING OR OTHER OPERATIONS

Chaves, New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTES OR INSTRUCTIONS TO

ACCOMPANYING REPORT OR

TYPE OF WORK DESCRIBED

WELL OR BORES CORED

DATES DRILLED

DEPTHS OF WELL

PRACTICAL TEST

MULTIPLE OR SINGLES

TESTS OR TREATMENT

ACCOMPLISHED

DRILL OR ACTIVITIES

ABANDONED

REWORK OR ABANDONED

ABANDONED

REPAIR WELL

CHARGE PLATE

OTHER

OTHER

Other

(Please report results of completed and ongoing work.)

(Please report results of completed and ongoing work.)

(Please report results of completed and ongoing work.)

17. REPORTS RELATING TO COMPLETED OPERATIONS: (Check only those all pertinent details and give pertinent dates, including initial and date of starting any pertinent work. If well is subsequently drilled, new information furnished will supersede old one excepted, except for all workers had prior permission to this work.)

A rig was moved in on Sept. 7th and the casing cut off and 966' pulled.
A 30 sx cat. plug was spotted from 916' to 1016'. Another 30 sx plug
was spotted from 193' to 293'. A 5 sx plug was spotted in the top and
a steel marker installed. A 9.6# mud laden fluid was used in spotting
the plugs.

18. I hereby certify that the foregoing is true and correct.

SIGNED

R. K. Belcher

TITLE Vice President Prod.

DATE 9/10/74

(This space for Federal or State office use.)

APPROVED

ED

TITLE

DATE

(Indicate if approval is given)

AD

See Instructions on Reverse Side