

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
Artesia, NM 88220

Budget Bureau N. 1001
Expires August 31, 1985
LEASE DESIGNATION AND PERIOD *c/57*

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different depth.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. WELL TYPE: ☐ GAS ☐ WELL ☐ OTHER ☒ Dry Hole

2. NAME OF OPERATOR
McClellan Oil Corporation

3. ADDRESS OF OPERATOR
P.O. Drawer 730, Roswell, NM 88202

4. LOCATION OF WELL (Report location clearly and in accordance with any state requirements.
See also space 17 below.)
At surface

2310' FSL & 2310' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether of RT OR G.L.)

3804' G.L.

5. LEASE NO. NM-27800

6. IF INDIAN, ALLOTTEE OR THIRD PARTY

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

MOC Mullis Fed.

9. WELL NO.

2

10. FIELD AND POOL OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 21-T15S-R29E

12. COUNTY OR PARISH 13. STATE

Chaves

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

Other

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON

CHANGE PLANS

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT

X

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE DEEPEND OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

5/2/86: Deepened to 1960'. Logged with Schlumberger Gamma Ray-Neutron. Plugged and abandoned (per verbal approval from Peter Chester) as follows:

1st plug - 25 sx from 1600' to 1704'.

2nd plug - 25 sx from 900' to 1000'.

3rd plug - 50 sx from 226' to 326'. WOC - 1 hour. Tagged plug with Howco wireline at 221'.

4th plug - 25 sx from 0 to 50'. Installed dry hole marker. Will clean and level location when pits dry.

18. I hereby certify that the foregoing is true and correct

SIGNED

Paul Sagdala

TITLE Operations Manager

DATE 5/5/86

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED
PETER W. CHESTER

JUL 31 1987

BUREAU OF LAND MANAGEMENT
ROSWELL RESOURCE AREA

*See Instructions on Reverse Side