


IL CONSERVATION DIVISIC
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	<input checked="" type="checkbox"/>
LAND OFFICE	<input checked="" type="checkbox"/>
OPERATOR	<input checked="" type="checkbox"/>



5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>	
5. State Oil & Gas Lease No. K4321	
7. Unit Agreement Name	
8. Farm or Lease Name Alto State	
9. Well No. 1	
10. Field and Pool, or Wildcat Double L Queen Assoc	
12. County Chaves	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☐ GAS WELL ☒ OTHER-
2. Name of Operator
Marnel Pipe & Supply Co.
3. Address of Operator
P. O. Box 1037, Artesia, N.M. 88210
4. Location of Well
UNIT LETTER G 1980 North 1980
THE East LINE, SECTION 1 TOWNSHIP 15S RANGE 29E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)
3874 gr. 3873.1'

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 2007 PBTD 1982
Csg. 8-5/8" 340-225 sx circ.
4 1/2" 2007 - 500 sx cir.
Perfs. 1938-50
P&A 8-4-83 Ran 2 3/8" tubing to 1950 and filled hole to surface with 165 sacks class C cement in two stages, set dry hole marker. Location ready for inspection. Plugging witnessed by B. W. Weaver.

Best ID-2
9-2-83
P&A

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>W. A. Gressitt</u>	TITLE <u>Consultant</u>	DATE <u>8-25-83</u>
APPROVED BY <u>Chamly Brook</u>	TITLE <u>Geologist</u>	DATE <u>8-24-85</u>

CONDITIONS OF APPROVAL, IF ANY: