

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 01703
35-015-01715

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No. B11538-1

7. Lease Name or Well/Segment Name
Empire Unit "H"

8. Well No. O. C. 35

9. Pool name or wellhead office
Empire Abo

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
ARCO OIL AND GAS COMPANY

3. Address of Operator
P. O. Box 1610, Midland, Texas 79702

4. Well Location
Unit Letter O : 969.94 Feet From The South Line and 2274.16 Feet From The East Line
Section 34 Township 17S Range 28E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-9-90. RU PU. P&A as follows:

Plug	Interval	Cmt.	Remarks
1	5720-6114	40 sx	Set CIBP at 6114. Press test csg to 500#. Ran CBL f/5000-4400. Spotted 40 sx on top of CIBP.
2	4765-5011	25 sx	Spot
3	3700-3946	25 sx	Perf at 3820. Unable to pump into. Spot 25 sx Cmt.
4	2237-2469	25 sx	Perf at 2360. Unable to pump into. Spot 25 sx Cmt.
5	1392-1530	60 sx	Perf at 1530. Set CR at 1434. Sqz'd w/60 sx. Dmpd. 42' cmt on CR.
6	Surf- 856	730 sx	Perf at 856. Cmt csg inside & outside to Surf.

5-11-90. P&A'd. Installed Dry Hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ken W. Gosnell TITLE Engr. Tech. DATE 12-26-90

TYPE OR PRINT NAME Ken W. Gosnell 915/688-5672 TELEPHONE NO.

(This space for State Use)

APPROVED BY Johnny Robinson TITLE OIL AND GAS INSPECTOR DATE 4-22-91

CONDITIONS OF APPROVAL, IF ANY

OK GW