

**N. M. O. C. & COM**  
UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN THE INDICATED  
(Other instructions on reverse side)

Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

Federal Bogle III-01146

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

---

7. UNIT AGREEMENT NAME

---

8. FARM OR LEASE NAME

Federal Bogle Federal

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT

Square Lake

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 29, T-16-S, R-30-E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

1. OIL WELL  GAS WELL  OTHER

2. NAME OF OPERATOR

Humble Oil & Refining Company

3. ADDRESS OF OPERATOR

P. O. Box 2100, Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\* See also space 17 below.)  
At surface

3300' North of South Line and 660' West of East Line of Sec. 29, T-16-S, R-30-E, Eddy County, New Mexico

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3753 G. R.

16.

**Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data**

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

Plug  ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

1. Set cement plug from 2976' to 2780' with 25 sacks.
2. Cut 5" casing at 1230' and pull same.
3. Set cement plug from 1280' to 1180' with 21 sacks.
- \* 4. Place cement plug from 555' to 505' with 15 sacks.
5. Set cement plug from 20' to 0 with 6 sacks.
6. Mud laden fluid between all plugs.
7. Install marker as required by New Mexico Oil Conservation Commission.

\* Approved subject to:

Increasing the length of this plug to - 400 - 500.

RECEIVED

AUG 10 1965

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Dist. Adm. Supvr.

DATE

August 10, 1965

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

AUG 11 1965  
RUDOLPH C. BAIER, JR.  
ACTING DISTRICT ENGINEER

TITLE

DATE

\*See Instructions on Reverse Side