

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS)

RECEIVED

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Drilling	7. Unit Agreement Name
2. Name of Operator Atlantic Richfield Company	8. Farm or Lease Name H.W. Hornbaker
3. Address of Operator P. O. Box 1978, Roswell, New Mexico	9. Well No. 1
4. Location of Well UNIT LETTER O 510 FEET FROM THE South LINE AND 1680 FEET FROM THE East LINE, SECTION 20 TOWNSHIP 17-S RANGE 26-E NMPM.	10. Field and Pool, or Wildcat Wildcat-Morrow
15. Elevation (Show whether DF, RT, GR, etc.) 3402' DF	12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Drilled a 7-7/8" hole to a T.D. of 8755' without encountering commercial hydrocarbons. We propose to P & A by setting the following neat Incor cement plugs.

30 sx from 8375-8475
30 sx from 6475-6575
30 sx from 5450-5550
30 sx from 4225-4325

30 sx from 2250-2350
40 sx from 1375-1475
30 sx from 500-600
10 sx in top of well

9.1#/gal mud will be used to spot all plugs. 8-5/8" surface casing will remain intact. A dry hole marker will be erected and location cleared and levelled.

Verbal permission received for above program from Mr. W. A. Gressett.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Original Signed

O. D. Bretches

SIGNED

TITLE **Dist. Drlg. Supervisor**

DATE **8-3-66**

APPROVED BY *M. L. Armstrong*

TITLE **OIL AND GAS INSPECTOR**

DATE **AUG 5 1966**

CONDITIONS OF APPROVAL, IF ANY: