							
NO. OF COPIES RECEIVE	0 3				Form C-103		
DISTRIBUTION		, ş	ECEIVE	7	Supersedes Old		
SANTAFE		NEW MEXICO OIL CONS	ERVATION COMMISSIC	N N	C-102 and C-103 Effective 1-1-65		
FILE	1 1						
U.S.G.S.	7		JAN 8 0 1979		5a. Indicate Type of	Lease	
LAND OFFICE					State X	Fee	
OPERATOR	,			ŀ	5. State Oil & Gas L		
			ARTERIA OFFICE		K 3630	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
	SUNDBY NO.	TICES AND DEPORTS ON			***********	mmm	
(DO NOT USE THE	S FORM FOR PROPOSALS	TICES AND REPORTS ON TO DRILL OR TO DEEPEN OR PLUG B.	ALK IU A DIFFFRENT BESERI	OIR.			
1.	USE MAPPLICATION FOR	PERMIT -** (FORM C-101) FOR SUC	H PROPOSALS.)			7711111111	
OIL	GAS X				7. Unit Agreement N	ume	
2. Name of Operator	WELL CES OTH	HER-	, , , , , , , , , , , , , , , , , , ,		8. Farm or Lease No		
		Danie - 1 Company	,	[
3. Address of Operator	<u> </u>	Pennzoil Company 🗸			Aid State	Com.	
o, manees of operator	ь о	7000 11:13		_	9. Well No.	-	
4. Location of Well	P. U.	Drawer 1828 - Midla	ind, lexas /9/0	2			
4. Location of well					10. Field and Pool,	f	
UNIT LETTER	660	FEET FROM THE North	LINE AND	FEET FROM	Aid Morro	w Gas	
				[
тне <u>East</u>	LINE, SECTION	24 TOWNSHIP 17-S	RANGE 28-E	NMPM.			
		15. Elevation (Show whether .	DF, RT, GR, etc.)		12. County	Milli	
		3727'	GR.		Eddy	<i>(11111111</i>	
16.	Check Approx				<u>V</u> <u>N</u>	<i></i>	
NC		priate Box To Indicate N					
NC	TICE OF INTENT	TON TO:	Su	BSEQUENT	REPORT OF:		
		()				r—	
PERFORM REMEDIAL WORK		PLUG AND ABANDON	REMEDIAL WORK		ALTERING	CASING	
TEMPORARILY ABANDON			COMMENCE DRILLING OPNS		PLUG AND	ABANDONMENT	
PULL OR ALTER CASING		CHANGE PLANS	CASING TEST AND CEMENT			dt	
			OTHER Draue	ineau pre	ssure survey	X	
OTHER							
17. Describe Proposed o	r Completed Operation	s (Clearly state all pertinent deta	ils and give pertinent day	es including e	estimated data of star	tina nau paguard	
work) SEE RULE 11	03.		The grow pertunction was	es, menang e	stimuted date of star	ting any proposed	
1 05 70	5 1 1 1 5						
1-25-79	1-25-79 Bradenhead Pressure Survey witnessed by N.M.O.C.C. representative						
	Mr. B. W. Weaver						
	13 3/8" x 8 5/8" Bradenhead - no pressure observed (cemented to surface)						
8 5/8" x 5 1/2" Bradenhead had 150 psi; Bled to 5 psi in 3 minutes.							
	5 1/2" x 2 3	/8" casing-tubing an	nulus - no pres	sure obse	rved. ,		
					,		
	D.u. M.b	ed to Surface	ok mo				
				1			
18. I hereby certify that	the information above i	is true and complete to the best o	f my knowledge and belief	•	······································		
	1						
L. C. ha	des 7/1634	Tes Marquart TITLE Dis	twict Duadwati-	n Mars	1 0	0.70	
SIGNED V	/L/ /Cliay	162 Marquart TITLE DIS	urica Productio	n manager	DATE 1-2	9-79	

OIL AND GAS INSPECTOR

FEB

1 1979

CONDITIONS OF APPROVAL, IF ANY