

NO. OF COPIES RECEIVED	4
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

RECEIVED

NOV 4 1974

SUNDY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT DEPTH OR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- ARTESIA, OFFICE		5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
2. Name of Operator Hanson Oil Corporation		5. State Oil & Gas Lease No.
3. Address of Operator Box 1515 Roswell, New Mexico 88201		7. Unit Agreement Name
4. Location of Well UNIT LETTER <u>I</u> , <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>34</u> TOWNSHIP <u>17-S</u> RANGE <u>26-E</u> N.M.P.M.		8. Farm or Lease Name Clyde Guy Comm.
15. Elevation (Show whether DF, RT, GR, etc.) N.K.		9. Well No. 1
		10. Field and Pool, or Wildcat Undes. Morrow
		12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input checked="" type="checkbox"/>	OTHER <u>By-pass junk in hole</u> <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

It is proposed to cut 5 1/2" casing off @ approx. 6000' & pull out of hole. Run drill pipe in 5 1/2" left in hole & spot a 300' plug @ 5750' to 6050', W.O.C. 24 hrs. Eastman Whipstock Inc. will then be used to by-pass junked casing & tubing in hole. Well will be drilled to a T.D. pf 8850'. 5 1/2" 17# casing will be run to T.D. & cemented with 350 sx. to bring cement to approx. 7000'. Perforating & stimulation will be as conditions require. Blow out preventers will be used.

APPROVAL VALID
FOR 90 DAYS UNLESS
DRILLING COMMENCED,

EXPIRES 1-5-75

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Ray Wilk TITLE Vice President- Prod. DATE 10-31-74

APPROVED BY W. A. Gressett TITLE OIL AND GAS INSPECTOR DATE NOV 6 1974

CONDITIONS OF APPROVAL, IF ANY:

Furnish copy to all offset operators