NO. OF COPIES RECE	IVEO 4			Form C-103
DISTRIBUTIO	N			Supersedes Old
SANTA FE		NEW MEXICO OIL	CONSERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
FILE	7/2			
U.S.G.S.		IA AV	1 9 1977	5a. Indicate Type of Lease
LAND OFFICE		MAT	13 13//	State X Fee
OPERATOR			·	5, State Oil 6 Gas Lease No.
696			. C, C,	B-8617
	SUNDR	Y NOTICES AND REPORT	SIA, OFFICE S ON WELLS	
(DO NOT USE	THIS FORM FOR PRO		PING BACK TO A DIFFERENT DESCRIPTION	
i.				7. Unit Agreement Name
OIL X	GAS WELL	OTHER*		
2. Name of Operator	V		•	8. Farm or Lease Name
S. P. Y	ates *	·		Spurck F State
3. Address of Operato)r			9. Well No.
207 So.	4th St., 3	Artesia, NM 8821	0	5
4. Location of Well				10. Field and Pool, or Wildcat
	т. 1	980 FEET FROM THE SOU	th 660	Red Lake
UNIT LETTER		FEET FROM THE	LINE AND FEET FR	THE THE THE THE MACHINE
West		n 16 TOWNSHIP	17S 28E	
THE	LINE, SECTIO	NTOWNSHIP	RANGE NM	(
	THITTHE	15. Elevation (Show w	hether DF, RT, GR, etc.)	12, County
		3560'	GR	Eddy ()
16.	Charle	Annoncies Pou To Islia	- Name of Maria	
			ate Nature of Notice, Report or	
	NOTICE OF IN	TENTION TO:	SUBSEQUE	INT REPORT OF:
			· [-1]	
PERFORM REMEDIAL W	Ħ	PLUG AND ABANDON		ALTERING CASING
TEMPORARILY ABANDO			COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASIN	• []	CHANGE PLANS	CASING TEST AND CEMENT JOB	r
			OTHER Plug Back	
OTHER			- L-J	
17. Describe Propose	ed or Completed Op	erations (Clearly state all pertine	nt details, and give pertinent dates, includ	ing estimated date of starting any proposed
work) SEE RULE	£ 1 f03.			
4/25/77	Pulled r	ods & tubing, set	wireline plug at 245	0' and dumped 15' ceme
1,23,11			nd perforated 1927-37	
		1703-14/11 shots		120 511005, 1000 1000,
	J Bhotb,	2,00 21,21 000	•	
4/26/77	Treated	with 1500 gals 15	% NE 3 BPM at avg 135	O psi max 1500 psi.
1, 20, 7,	110000			Pon man acco pent
4/27/77	Frac'd w	ith 45000 gal tre	ated water, 32000# 20	/40 and 11000#
-/ / - /	10/20 sa	-		
	20,20 54			
4/28/77	Bled bac	k. circulated sam	d off plug - pulled p	acker and plug. Ran
1/20/11	4/28/77 Bled back, circulated sand off plug - pulled packer and plug. Ratbg and rods - put on pump test.			
	cbg and	roas pac on pan	p cesc.	
			·	·
18. I hereby certify th	hat the information	above is true and complete to the	best of my knowledge and belief.	
/	1		,	
	' //		Agent	5/18/77
SIGNED TAN	un pler	nandley TITLE	2190110	DATE J/ LO///
		, 0		–
2.	10.4	1011.	SUPERVISOR, DISTRICT H	MAY 2 0 1977
ADDROVED BY	1,U,X+	- WELLE TITLE	SOLDER MOR, DIDIRIUL M	DATE