CUNDRY NOTICES AND DEPONTS ON WELLS	NM 3603
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to dependent reservoir. Use "APPLICATION FOR PERMIT" for such proposals.	6. IF INDIAN, ALLOTTER ON TRIDE NAME
I. OIL GAS WELL OTHER OCT -	ED 7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR	8. FARM OR LEASE NAME
Yates Petroleum Corporation U.S. GEOLOGIO	• Federal "GC"
2. NAME OF OPERATOR Yates Petroleum Corporation U.S. GEOLOGICAL SUR 3. ADDRESS OF OPERATOR 207 South 4th Street - Artesia, NM 88210 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements	RVEV D. WELL NO.
207 South 4th Street - Artesia, NM 88210" MEXIC 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.	
See also space 17 below.)	10. FIELD AND POOL, OR WILDCAT Und
660° FSL & 660° FEL of Sec. $32-17S-25E$	1_ Silaron
RECEIVE	D 11. SEC., T., R., M., OR BLK, AND NURVEY OR AREA
	Sec. 32-17S-25E Unit P NMPM
14. FERMET NO. 15. ELEVATIONS (Show whether DF, RT, CA CC) 27 1976	12. COUNTY OB PARISH 13. STATE
3588' GR	
.6. Check Appropriate Box To Indicate Nature of Notice Perce	rt, or Other Data
	SUBSEQUENT REPORT OF:
TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT MULTIPLE COMPLETE FRACTURE TREATMENT	
SHOOT OR ACIDIZE ABANDON* SHOOTING OR ACIDIZE	
REPAIR WELL CHANGE PLANS (Other) TA Mrw	vr & comp Strawn X
	results of multiple completion on Well Recompletion Report and Log form.)
 DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent proposed work. If well is directionally drilled, give subsurface locations and measured and true nent to this work.)* 	it dates, including estimated date of starting any e vertical depths for all markers and zones perti-
TD 8400'; PBTD 8292' $(9-20-76)$ - Moved in Pulling Plug in packer at 8166' to temporarily abandon th tubing. RIH w/Tubing Conveyed Gun on tubing w/Gu at 7796'. Perforated the Strawn formation 7854-7 in 5" TSTM - Prep to treat. <u>9-21-76</u> - Treated perforations 7854-7864' w/1000 w/nitrogen. Flowed well back and cleaned up at 3 run Bottom Hole Pressure Bomb. SITP 2319# after 2886#. <u>9-25-76</u> - MICU, cleaned well up and pulled Tubine Frac well. <u>9-29-76</u> - Rigged up and went in hole w/2-3/8" tu Guiberson packer at 7802'. Sand Frac'd w/10000 ga and CO2 and 10000# 20-40 sand. Flowed back load. flowed 265# on 1/4" choke = 400 MCFPD.	he Morrow formation. Pull hiberson Uni-VI packer se 7864' w/60 .32" holes. GT gallons of 7½% acid 55# on 1/2" choke. Si to 86 hours. BHP at 7830' ag Conveyed Gun. Prep to bing and packer. Set gallons of 3% gelled acid
S. I hereby certify that the foregoing is true and correct SIGNED	DATE 0-20-76
	DATE 0-20-76

*See Instructions on Reverse Side

٠