

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Geology, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-015-22776
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	EMPIRE ABO UNIT "F"
8. Well No.	382
9. Pool name or Wildcat	EMPIRE - ABO

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
ARCO OIL & GAS COMPANY

3. Address of Operator
BOX 1710, HOBBS, NEW MEXICO 88240

4. Well Location
Unit Letter F : 2400 Feet From The NORTH Line and 1600 Feet From The WEST Line

Section 35 Township 17S Range 28E NMPM County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3675.6' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☒
PULL OR ALTER CASING ☐
OTHER: ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TA & HOLD WELL BORE FOR FIELD BLOW DOWN

1. Notify NMOCD 24 hrs. prior to testing CIBP
2. MIRU
3. Unset PKR or TAC
4. Install BOP & GIH to tag PBTD
5. POH w/TBG, TOH
6. GIH w/TBG or WL set CIBP
7. Set CIBP maximum 50' above existing PERFS
8. POH w/1 Jt. & circ a mix of 2 gal WT675 chem. per 10 bbls 8.6# brine
9. When circulation is established, w/ treated fluid at surface, test CIBP to 500# and cut chart.
10. POH, laying down - leave 1 Jt. hanging on BI Bonnett

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Administrative Supervisor DATE March 11, 1991
TYPE OR PRINT NAME TELEPHONE NO.

(This space for State Use)

APPROVED BY [Signature] TITLE Field Rep DATE 4/8/91

CONDITIONS OF APPROVAL, IF ANY:

Notify N.M.O.C.C. in sufficient time to witness

Testing CIBP