

Submit 3 Copies
to Administrative
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1910, Hobbs, NM 88240

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 RG Drive N.E., Aztec, NM 87410

WELL API NO. 3001522817
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. E-7832
7. Lease Name or Unit Agreement Name EMPIRE ABO UNIT "E"
8. Well No. 362
9. Field name or Wellhead EMPIRE ABO

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL ☒ GAS WELL ☐ OTHER ☐	RECEIVED JAN 22 '90 C. C. D. ARTESIA, OFFICE
2. Name of Operator ARCO Oil and Gas Company	
3. Address of Operator Box 1710, Hobbs, New Mexico 88240	
4. Well Location Unit Letter A : 1200 Feet From The NORTH Line and 1200 Feet From The EAST Line Section 34 Township 17S Range 28E NE4PM EDDY County 10. Elevation (Top of casing, DF, F&B, RT, GR, etc.) 3675.9 GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☒	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOBS ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TA & HOLD WELL BORE FOR FIELD BLOW DOWN
START WORK ON APPROVAL

Procedures as follows:

1. MIRU DDPV
2. Give NMOCD 24 hr notification of pressure test on csg
3. RIH w/swab to clear tbg
4. Install BOP & POH w/tbg & ACC
5. RIH w/CIBP on tbg
6. Set CIBP @ ±6115
7. POH w/1 jt
8. Pump 105 BBLS 8.6# brine w/2 gal WT 675/10 BF to establish circulation
9. SI Rams on BOP & press. test to 5-0#. Install chart
10. POH, laying tbg down. Leave 1 jt on flange
11. RDCL. Close all tbg, csg, surface csg valves

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE: James D. Cogburn TITLE: Administrative Supervisor DATE: 1-19-90
TELEPHONE NO.: 392-3551

(This space for State Use) ORIGINAL SIGNED BY
MIKE WILLIAMS
SUPERVISOR, DISTRICT II
APPROVED BY: _____ TITLE: _____ DATE: _____
COORDINATOR OF APPROVAL, IF ANY: _____

JAN 23 1990

FIELD	OPERATOR		DATE
EMPIRE ABO	ARCO OIL & GAS CO		1-18, 90
LEASE	WELL NO.	LOCATION	
EMPIRE ABO UNIT "E"	362	UNIT A, SEC 34, T. 17S, R. 28E	

8 5/8 " CASING SET AT 750 ' WITH 650 SX OF
 _____ CEMENT HOLE SIZE 11 " TOC @ SURF '

5 1/2 " CASING SET AT 6343 ' WITH 1750 SX OF
 _____ CEMENT HOLE SIZE 7 7/8 " TOC @ SURF '

TOTAL DEPTH 6350
 CROP @ 6200
 PERFS 6124 - 6136