

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE 'APPLICATION FOR PERMIT'
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

Diamond Back Petroleum, Inc.

3. Address of Operator

Ruidoso, NM

4. Well Location

Unit Letter L : 1980 Feet From The South Line and 660 Feet From The West Line

Section 7 Township 17-S Range 28-E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

REMEDIAL WORK ☐

ALTERING CASING ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☒

PULL OR ALTER CASING ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Spot 25sxs cement plug at 1100' and tag.
2. Load hole with mud.
3. Spot cement from 405' to surface and set P&A marker.

Post ID-2
1-19-96
P&A

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Raymond Maldonado

TITLE Supervisor

DATE 12-21-95

TYPE OR PRINT NAME

TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY TIM W. GUM
DISTRICT II SUPERVISOR

APPROVED BY _____ TITLE _____

DATE DEC 26 1995

CONDITIONS OF APPROVAL, IF ANY:

New Mexico

ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

7/28/95

Diamondback Petroleum Inc.
Martha #1 L-7-17-28

10 3/4 set at 355' cemented with 375 Sx c
4 1/2 set at 2382' cemented with 600 Sx and did not circulate.
Top of cement at 650'. Run 1" pipe and circulated cement to pit.
Perfs 1170-1218, 2159-2338
2 3/8 @ 2342'

1. Spot a 25 Sx plug at 1100' and tag.
2. Pull up hole to 405' and bring cement to surface.
3. Set dry hole marker.
4. Mud will be between plugs.

Contractor will need to make assessment of roads and location
and do whatever dir work is required.

