Form 9-331 IIAII IN CTATEC Drawe	IL CONS. COMMISS!	1
DEPARTMENT OF THE INTER	OR verse side 210	5. LEASE DESIGNATION AND SERIAL NO.
GEOLOGICAL SURVEY		NM 9987 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS C (Do not use this form for proposals to drill or to deepen or plug by Use "APPLICATION FOR PERMIT—" for such pr	ack to a different reconnects	
GIL GAS OTHER WELL XX WELL OTHER 2. NAME OF OPERATOR	RECEIVED BY	7. UNIT AGREEMENT NAME
Fred Pool Drilling, Inc.	AUG 20 1986	8. FARM OR LEASE NAME Max Federal 9. WELL NO.
P.O.Box 1393, Roswell, N.M. 8820	O. C. D.	3
LOCATION OF WELL (Report location clearly and in accordance with any See also space 17 below.) At surface	State regulrements.	10. FIELD AND POOL, OR WILDCAT
330 FWL 2310 FNL SW/4 NW/4		East Red Lake
4. PERMIT NO. 15. ELEVATIONS (Show whether DF,	RT CR atc.)	Sec. 30-16S-29E 12. COUNTY OR PARISH! 13. STATE
30-015-25557 3692 Gr	ni, da, co.,	Eddy N.M.
6. Check Appropriate Box To Indicate No.	ature of Notice, Report, o	
NOTICE OF INTENTION TO:	SUBS	EQUENT REPORT OF:
TEST WATER SHUT-OFF PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL,
FRACTURE TREAT SHOOT OR ACIDIZE ABANDON*	FRACTURE TREATMENT SHOOTING OR ACIDIZING	X ALTERING CASING
REPAIR WELL CHANGE PLANS	(Other)	ABANDON MENT*
(Other) 7. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent proposed work. If well is directionally deliled, give subsection least.	Completion or Recor	ults of multiple completion on Well mpletion Report and Log form.)
August 12,1986: Perforated 1828'-1838	8' with !4 shots	
Acidized with 250 gal Frac with 30,000 gal 20/40 sand and 25,000 and 15 BPM. ISIP=1200	llons 15% HCL ac lons gel water, 0# 12/20 sand, 1	cid. 20,000# 1300 PSI
Put well on pump to a	recover load.	
ACCEPTED FOR RECU	rKU	RUM
AUG 19 1986	r	AUS 1 4 1905
Live	r	AUG 1 + 1905
AUG 19 1986 CARLSBAD, NEW ME	r	AUG 1 4 1905
AUG 19 1986 CARLSBAD, NEW MES	r	DATS = 13-86

Y8 C.37 1.727

- C 100

9