

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

CISF
UP
Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.
30-015-30577

Indicate Type of Lease
STATE FEE

State Oil & Gas Lease No.

Lease Name or Unit Agreement Name

Oxy Malt-O-Meal State

Well No.
1

Pool name or Wildcat
Wildcat

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMITS TO DRILL - ARTESIA" (FORM C-101) FOR SUCH PROPOSALS.)

Type of Well:
OIL WELL GAS WELL OTHER SWD

Name of Operator
SDX Resources, Inc.

Address of Operator
PO Box 5061, Midland, TX 79704

Well Location
Unit Letter L 1800 Feet From The South Line and 660 Feet From The West Line
Section 22 Township 17S Range 28E NMPM Eddy County

Elevation (Show whether DF, RKB, RT, GR, etc.)
3610 GR

11
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ANBANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER: Re-Enter as a SWD well <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER: <input type="checkbox"/>

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Oxy USA Inc. P&A this well in 1999.
SDX Resources, Inc. proposes to re-enter well for SWD as follows:
Remove marker & stub onto 8-5/8" intermediate csg. Drill out plugs w/7-7/8" bit to 8150'. Run 5-1/2" csg & circ cmt to surf. Perf & acidize selective perms 7250-8120. Run 2-7/8" PC tbg w/PC pkr to 7200'. Circ pkr fluid. Set pkr & test csg.
C-108 pending.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.
SIGNATURE Bonnie Atwater TITLE Regulatory Tech DATE 03-30-01
TYPE OR PRINT NAME Bonnie Atwater TELEPHONE NO. 915/685-1761

(This space for State Use)
APPROVED BY Record Only TITLE _____ DATE 4/9/01
CONDITIONS OF APPROVAL, IF ANY: