

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO.

30-015-31220

Indicate Type of Lease

STATE

FEE ☒

State Oil & Gas Lease No.

Lease Name or Unit Agreement Name

Logan Draw 19 Federal Com

Well No.

1

Pool name or Wildcat

Logan Draw; Morrow (Gas)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

Type of Well:

OIL

WELL ☐

GAS

WELL ☐

OTHER P&A'd

Name of Operator

Nearburg Producing Company /

Address of Operator

3300 N A St., Bldg 2, Suite 120, Midland, TX 79705

Well Location

Unit Letter

P

810

Feet From The

South

Line and

740

Feet From The

East

Line

Section

19

Township

17S

Range

27E

NMPM

Eddy

County

Elevation (Show whether DF, RKB, RT, GR, etc.)

3341' GR

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING

COMMENCE DRILLING OPNS. ☐

PLUG AND ANBANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.


11/02/01 Set 5-1/2" CIBP @ 7500', cap w/ dump bailer w/ 35' cmt.

11/05/01 Circ hole w/ mud.

11/06/01 Stretch csg, showed 5833' free, cut and POOH w/ 5850' of 5-1/2" csg. Spot 85 sx cmt. 5990-5680'.
Covering stub plug and the Wolfcamp.

11/07/01 Tag Wolfcamp plug @ 5522', spot 50 sx 4690-4580', calc, TOC @ 4475'. Spot 50 sx 2654-2530', calc.
TOC @ 2439'. Spot 50 sx cmt, 1614-1534'. calc, TOC @ 1412', tag cmt @ 1479', spot 10 sx 30' to surface.

11/07/01 Install dry hole marker and clean location.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Kim Stewart

TITLE Regulatory Analyst

DATE 11-27-2001

TYPE OR PRINT NAME Kim Stewart

TELEPHONE NO. 915/686-8235

(This space for State Use)

APPROVED BY

Gerry Guye

TITLE

Gerry Guye

Compliance Officer

DATE

10-8-02

CONDITIONS OF APPROVAL, IF ANY:



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

GARY E. JOHNSON

Governor

Jennifer A. Salisbury

Cabinet Secretary


Lori Wrotenbery

Director

Oil Conservation Division

11/30/01

Nearburg Producing Co.
3300 N A St., Bldg 2, Suite 120,
Midland, Texas 79705



Form C-103 Report of Plugging for your Logan Draw 19 Fed. Com. # 1 P-19-17-27 30-015-31220
Cannot be approved until an NMOCD representative has made an inspection of the location and found it to
be cleared to comply with OCD rules and regulations. Please check each item in the space provided to
indicate that the work has been accomplished and the location is ready for final inspection.

- ☒ 1. All pits have been filled and leveled.
- ☒ 2. Rat hole and cellar have been filled and leveled.
- ☒ 3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in
concrete to mark the exact location of the plugged well. (Marker must have operator name, lease name,
well number and location including quarter/quarter section or unit letter, section, township, range and API
well ID number permanently welded, stamped or otherwise engraved into the metal marker.)
- ☒ 4. The location has been leveled as nearly as possible to original top ground contour and has been
cleared of all junk and equipment.
- ☒ 5. The dead men and tie downs have been cut and removed.
- ☒ 6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been
leveled and cleared of all junk & equipment.
- ☒ 7. All environmental concerns have been addressed as per OCD guidelines.

The above are minimum requirements and no plugging bond will be cancelled until all locations for
plugged and abandoned wells have been inspected and Form C-103 approved.

When all of the work outlined above has been done, please notify this office by completing, signing and
returning this letter to us so that our representative will not have to make more than one trip to the location.

I certify that the above work has been done and the above-mentioned lease is ready for OCD inspection and
approval.

Name

Van Barton
Field Rep. II

Title