

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-015-32387

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
VO-5549

7. Lease Name or Unit Agreement Name
GRIZZLY BEAR ST. COM.

8. Well No.
1

9. Pool name or Wildcat
EMPIRE MORROW SOUTH

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☒ OTHER

2. Name of Operator
MURCHISON OIL & GAS, INC. (015363)

3. Address of Operator
1100 MIRA VISTA BLVD. PLANO, TX. 75093-4698

4. Well Location
Unit Letter 0 : 810 Feet From The SOUTH Line and 1800 Feet From The EAST Line
Section 1 Township 17S Range 28E NMPM EDDY County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐		CASING TEST AND CEMENT JOB ☒	
OTHER: ☐		OTHER: ☐	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Drill 12-1/4" hole to a depth of 2445'. Run casing as follows:

	Float Shoe	1'
1 Jt	9-5/8" 47 #/FT N-80 LTC	37'
	Float collar	1'
66 Jts	9-5/8" 47 #/FT N-80 LTC	2428'
	TOTAL	2467'

Set casing @ 2445'. Cement with 1400 SX 35/65 + 2% CaCl + 1/4 # Celloflakes followed with 200 SXS Class "C" + 2% CaCl. Circulate 250 SXS to pit. Bump plug and floats held. Could not set slips. Cut off 13-3/8" head and weld on 9-5/8" head. Nipple up BOP and test to 5000 psi. Test OK. Drill out cement floats and plug. Resume drilling formation with 8-1/2" bit.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Michael S. Daugherty TITLE VICE PRESIDENT OPERATIONS DATE 9/9/02
TYPE OR PRINT NAME MICHAEL S. DAUGHERTY TELEPHONE NO. (972) 931-0700

(This space for State Use)

ORIGINAL SIGNED BY TIM W. GUM
DISTRICT II SUPERVISOR

SEP 17 2002

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: