

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIP DATE*
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-7752

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Root Fed.

9. WELL NO.

#1

10. FIELD AND POOL, OR WILDCAT

Square Lake

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 1-17S-29E

12. COUNTY OR PARISH 13. STATE

Eddy

N. Mex.

1. OIL WELL ☐ GAS WELL ☐ OTHER Oil well converted to disposal well.

2. NAME OF OPERATOR

AMCO Production Co. ✓

3. ADDRESS OF OPERATOR

Box 727, Artesia, New Mex. 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

Sec. 1, T17S - R29E

SE/4 - NE/4 Unit "F"

1650' FNL - 1980' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3678

O. C. C.

ARTESIA, OFFICE

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐

(Other) Plug & Abandon

PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Intention is to plug and abandon well.

Will cover perforations at 2450 to 2550 with 25 sacks. 100 ft. plug.
Will cut and pull 5½" casing at approximately 1500'. Will set 100' plug
with 25 sacks where pipe is cut. Will set 100' plug at base of 8 5/8"
with 25 sacks. Do not intend to pull any 8 5/8" pipe. Set 10 sack plug
at surface with marker.

If well is flowing back will set cast iron plug in 5½" casing, 50'
above perforations. Plus at least 35' cut on BP

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Agent

DATE 11-18-74

(This space for Federal or State office use)

APPROVED SUBJECT TO POSSIBLE ADDITIONAL
REQUIREMENT THAT PAD AND/OR ROAD
BE RIPPED AND SEEDED

*See Instructions on Reverse Side

CONTACT THIS OFFICE REGARDING ABOVE
BEFORE MAKING FINAL CLEANUP.

RECEIVED

DEC - 5 1974

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

APPROVED

DEC 6 - 1974

H. L. BEEKMAN

ACTING DISTRICT ENGINEER

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.