

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office 00000000

Lease No. 325

Unit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

19 197

Well No. 5 is located 120 ft. from N line and 110 ft. from E line of sec. 20

County 31-100	Sec. 10	17	17	17
(4 Sec. and Sec. No.)	(Twp.)	(Range)	(Meridian)	
Indian				
(Field)	(County or Subdivision)	(State or Territory)		

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

November 6, 1977:

Notes, dated 3/6/51, indicate that the hole was drilled as generally being 950', and 10' of the cement plug at the top of the hole was 925', and the cement plug with 15' inside at each of the two holes was 975', and not an ordinary dry hole marker. Filled 900' of the hole with 10' of cement. This work was done by C. E. East, Contractor, and Mr. David, 3/11/51.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company DAVID SAFFIN

Address. William Johnson,

Assets Total 3140.

Art. 11, New Mexico

By Robert L. Cook

File "collected" post.