Form 9-331 (May 1963)

## TED STATES SUBMIT IN TR. NATE\* OR OTHER INTERIOR (Other Instructions on re-

Form approved. Budget Bureau No. 42-R1424.

	GEOLOGICAL S	LC 029395 (a)					
	SUNDRY NOTICES AND R (Do not use this form for proposals to drill or to do Use "APPLICATION FOR PERMIT	eepen or plug back	to a different reservoir.	6. IF INDIAN, ALL	OTTEE OR TRIBE NAME		
1.	OIL GAS WELL OTHER	7. UNIT AGREEMENT NAME					
2.	NAME OF OPERATOR	8. FARM OR LEASE NAME					
	Sinclair <sup>U</sup> il & Gas Company				Turner "A"		
3.	ADDRESS OF OPERATOR				9. WELL NO.		
	P. O. Box 1920, Hobbs, New Mexico 88240				9 .		
4.	OCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface			10. FIELD AND POOL, OR WILDCAT Grayburg Jackson			
	330' from the North line and 1980' from the East line				11. SEC., T., R., M., OR BLE. AND SURVEY OR AREA 19-T17S-R31E		
14.	PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)			12. COUNTY OR PA	RISH 13. STATE		
		36601	GR	Eddy	New Mexico		
16.	Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data						
	NOTICE OF INTENTION TO: SUBSE			QUENT REPORT OF:			
	FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other)  PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON* CHANGE PLANS X		WATER SHUT-OFF  FRACTURE TREATMENT SHOOTING OR ACIDIZING  (Other)  (Note: Report result Completion or Recom	REPAIRING WELL  ALTERING CASING ABANDONMENT*  Sof multiple completion on Well eletton Report and Log form.)			
17.	DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly stapproposed work. If well is directionally drilled, give a nent to this work.) *	ate all pertinent det subsurface locations	tails, and give pertinent dates and measured and true verti	s, including estimated cal depths for all ma	l date of starting any trkers and zones perti-		

Total Depth: 3423'. Presently producing 1 BOPD and 1 BWPD.

PROPCSE TO: Clean out if necessary to T.D. Load hole w/water and run Gamma Ray-Neutron Collar Log. Run tubing and packer and set @ approx. 28391. Convert from producing well to water injection well 2914-3423! open

hole in Grayburg Jackson, Russell-Turner Waterflood System.

RECEIVED
NOV2 1967 SURVET
NOV2 1967 SURVET
NOVE 1967 SURVET
NOVE 1967 SURVET
NOVE 1967 SURVET
NOVE 1967 SURVET

10 T househy contide that the formula to the					<del></del>	
18. I hereby certify that the foregoing is true and correct SIGNED		Engineer	-	DATE _	10-28-6	67
(This space for Federal or State office use) APPROVED BY	TITLE			DATE	NOV	2 1967
CONDITIONS OF APPROVAL, IF ANY:			<del></del> -			

\*See Instructions on Reverse Side

Orig&4cc: USGS, Artesia

cc: Regional Office

cc: file