

UNITED STATES M. O. C. COPY
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
SUBMIT IN TP (Other instruct
verse side) CATE* on re-Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 029395 (a)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Turner "A"

9. WELL NO.

19

10. FIELD AND POOL, OR WILDCAT

Fren Seven Rivers

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

19-17S-31E

12. COUNTY OR PARISH 13. STATE

Eddy

N.M.

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☒ GAS WELL ☐ OTHER ☐ Plug & Abandon

2. NAME OF OPERATOR

Atlantic Richfield Company ✓

3. ADDRESS OF OPERATOR

P. O. Box 1710, Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1980' FNL & 1980' FWL (Unit letter F)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3650' DF

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Plug & abandon

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Rigged up 2-9-76. POH w/rods & pump. Installed BOP. POH w/tbg. RIH w/tbg to 1839'. Spotted 35 sx C1 C cmt (120' plug) in bottom of 5½" csg. Tagged cmt plug @ 1716'. Circ hole w/heavy gelled mud. Free pt indicated 5½" csg free @ 950'. Shot off collar @ 950', rec 950' of 5½" OD csg. Spotted 35 sx C1 C cmt (100' plug) across 5½" csg stub @ 950'. Tagged top of plug @ 720'. 7" OD csg parted @ 280' & came w/5½" csg. Spotted 35 sx C1 C cmt plug across 7" OD csg shoe @ 494'. Tagged plug @ 220'. Spotted 80 sx C1 C cmt 220-surface. Installed regulation dry hole marker. Cleaned & levelled location. P&A eff 2/13/76. Final Report.

RECEIVED

MAR 16 1976

O. C. C.
ARTESIA, OFFICE

RECEIVED

FEB 20 1976

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Dist. Drlg. Supv.

DATE 2/19/76

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side