

N. M. O. C. C. COPY
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN _____ LICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐	7. UNIT AGREEMENT NAME Dow Unit
2. NAME OF OPERATOR Skelly Oil Company	8. FARM OR LEASE NAME Lynch "A"
3. ADDRESS OF OPERATOR Box 730 - Hobbs, New Mexico	9. WELL NO. No. 13
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1980' FWL & 1980' FWL of Section 22 17S - 31E	10. FIELD AND POOL, OR WILDCAT Grayburg Jackson
14. PERMIT NO. _____	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 22 - 17S - 31E
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3846' DF	12. COUNTY OR PARISH Eddy
	13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☒	ABANDON* ☐
REPAIR WELL ☐	CHANGE PLANS ☐
(Other) Convert Well to Water Injection	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
(Other) _____	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Move in and rig up Pulling Unit.
2. Pull rods, pump and tubing.
3. Perforate Premier Section of the Grayburg Jackson Zone from 3376-3392', 3404-3414', 3422-3428', 3441-3444' and 3456-3458' with two jet shots per foot for a total 37' and 74 holes.
4. Set Retrievable Bridge Plug at approximately 3460' and wash perfs. 3376-3458' (intervals) with 500 gallons Mud Acid.
5. Retrieve Bridge Plug and clean out with sand pump to total depth of 3571'.
6. We will then install Water Injection Equipment and inject water down 2-3/8" OD tubing under packer through 5-1/2" OD casing perfs. 3376-3458' and open hole section 3472-3571' into the Grayburg and San Andres Formations.
7. This well will be a water injection well in the Grayburg and San Andres Zones for the Dow Unit Area Waterflood Project in the Grayburg Jackson Pool, Eddy County, New Mexico.

RECEIVED

APR 13 1965

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICORECEIVED
APR 12 1965
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct


SIGNED (ORIGINAL SIGNED) H. E. Ash TITLE Dist. Supt. DATE April 6, 1965

(This space for Federal or State office use)

APPROVED BY _____
CONTINUOUS OR APPROVAL, IF ANY:

TITLE _____

DATE _____



*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

