



# NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

**GARY E. JOHNSON**  
Governor  
**Betty Rivera**  
Cabinet Secretary

**Lori Wrotenbery**  
Director  
Oil Conservation Division

File  
Copy

18 October 2002

The Wiser Company  
P. O. Box 2568  
Hobbs, New Mexico 88240

RE: Skelly Unit # 42                      B-22-17-31                      30-015-05356

Dear Sirs,  
Enclosed you will find a copy of the Form 3160 you sent to us. Please include the changes on another  
sundry notice 3160 and send to the BLM for approval.  
Thank you very much for your help in resolving this matter.

Respectfully,

Van Barton  
Field Rep.II

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE \*  
(Other Instructions on  
reverse side)

Budget Bureau No. 1004-0135  
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT - " for such proposals.)

1. OIL <input type="checkbox"/> WELL GAS <input type="checkbox"/> WELL OTHER <input type="checkbox"/> WIW - P & A	
2. NAME OF OPERATOR The Wiser Oil Company	
3. ADDRESS OF OPERATOR P.O. Box 2568 Hobbs, New Mexico 88240 (505) 392-9797	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface  660' FNL & 1880' FEL Unit B	
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3875' DF

5. LEASE DESIGNATION AND SERIAL NO. LC-029419-A	
6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
7. UNIT AGREEMENT NAME Skelly Unit	
8. WELL NO. 42	
9. API WELL NO. 30-015-05356	
10. FIELD AND POOL, OR WILDCAT Grayburg Jackson 7-Rivers-QN-GB-SA	
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 22-T17S-R31E	
12. COUNTY OR PARISH Eddy County	13. STATE NM

16. Check Appropriate Box to indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT OFF <input type="checkbox"/>	FULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
(Other) _____	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
(Other) _____	
(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS: (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Wiser Oil respectfully request approval to plug and abandon the well by the procedure listed below.

Surface Casing: 8-5/8" set @ 616' Production Casing: 4-1/2" set @ 3764' 11.60#

Perfs: 3188'-3606' 2283'-2400' CIBP @ 2100' & 3106' w/40 cement on plug

1. Spot 50' plug on CIBP @ 2100'
2. Tag cement plug.
3. Circulate pkr. fluid.
4. Perforate casing @ 620'. Circulate cement to surface. Leave a 50' plug @ 620' to 570'.
5. Tag cement.
6. Spot 50' cement plug to surface.
7. Install dry hole marker.
8. Clean location.

18. I hereby certify that the foregoing is true and correct.

SIGNED Mike Jones TITLE Superintendent

DATE October 7, 2002

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_

DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

\*See Instruction On Reverse Side



# NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

**GARY E. JOHNSON**  
Governor  
**Betty Rivera**  
Cabinet Secretary

**Lori Wrotenbery**  
Director  
Oil Conservation Division

20 September 2002

Wiser Oil Co.  
P.O. Box 2568  
Hobbs, New Mexico 88241

SEP 20 2002  
RECEIVED  
OCD - ARTESIA

Dear Sir:

The wells indicated on the attached list are scheduled for expiration of their 'Temporary Abandoned' status this year.

It is requested that you furnish this office with your future plans for all wells listed. These options may include:

1. Returning the wells to production, injection or disposal as appropriate.
2. Request extension of TA status and performing an MIT test (casing integrity test).
3. Submit a plan for plug and abandonment on form C-103.

Please notify this office as soon as possible of your intentions by submitting a Form C-103 for each well. The completed Form C-103 must be in our office on or before 30 days after the date of expiration for each well. If a request for extension is requested please be prepared to offer a date for testing.

Respectfully,

Van Barton  
Field Rep.II

API	Company	Well Name	Well Number	Sec	Twp	Rng	W/TYP	Appr End Dt
0-6879-10-30A	SUNBELT OIL & GAS INC.	BURNING TREE WPT	408					31 AUG - 2007

JUN 17 2002  
 RECEIVED  
 OGD - ARTESIA