

Form 9-331
(May 1963)UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN 2 PLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		5. LEASE DESIGNATION AND SERIAL NO. LC 029418-b
2. NAME OF OPERATOR Skelly Oil Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME -
3. ADDRESS OF OPERATOR Box 730 - Hobbs, New Mexico		7. UNIT-AGREEMENT NAME Skelly Unit
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1278' FSL & 660' FWL Section 23-178-31E		8. FARM OR LEASE NAME Skelly Unit
14. PERMIT NO. -	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3859' DF	9. WELL NO. 78
		10. FIELD AND POOL, OR WILDCAT Grayburg Jackson
		11. SEC., T., R., M., OR BLE. AND SURVEY OR AREA Sec. 23-178-31E
		12. COUNTY OR PARISH Eddy
		13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) **Clean Out and Treat**PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐☒

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Skelly Unit Well No. 78 is presently producing from open hole 3190-3673' in the Grayburg and San Andres Formations. We propose to clean out to original total depth of 3855' as follows:

1. Move in, rig up pulling unit, pull rods and tubing.
2. Clean out to T.D. 3855'.
3. Run Gamma Ray Neutron Log to 3855'.
4. Set 700' of 4 1/2" slotted liner at 3855'.
5. Wash open hole behind slotted liner with 750 gallons acid.
6. Run rods and tubing and return well to production status.

18. I hereby certify that the foregoing is true and correct

SIGNED **(Signed) V. E. Fletcher**TITLE **District Superintendent**DATE **August 9, 1967**

(This space for Federal or State office use)

APPROVED BY **H. L. BLEKMAN**
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side

RECEIVED
AUG 11 1967
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

RECEIVED

AUG 15 1967

O. G. G.
ARTESIA, N. M.

APPROVED
AUG 14 1967
H. L. BLEKMAN
ACTING DISTRICT ENGINEER

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

REMOVED TO FILE

APPROVED
JAN 14 1964
FEDERAL BUREAU OF INVESTIGATION
U.S. DEPARTMENT OF JUSTICE