

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	/
FILE	/
U.S.G.S.	
LAND OFFICE	
OPERATOR	/

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>

5. State Oil & Gas Lease No.
B-9563, B 10714, B-1266, B-255, B-514

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator	G-J West Coop. Unit
Tenneco Oil Company	8. Farm or Lease Name
3. Address of Operator	
Box 1031, Midland, Texas 79701	9. Well No.
4. Location of Well	51
UNIT LETTER 0, 560 FEET FROM THE south LINE AND 1980 FEET FROM	10. Field and Pool, or Wildcat
THE east LINE, SECTION 16 TOWNSHIP 17-S RANGE 29-E NMPM.	Grayburg-Jackson
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUS AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUS AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

PROCEDURE:

1. Pull rods & tubing. Move off pulling unit.
2. Perforate zones of interest w/one 3/8" jet per interval:
Lovington Sand, 2482, 2478
Premier Sand, 2377, 2374, 2369
Anderson Zone 6, 2361
Anderson Zone 5, 2343
Anderson Zone 4, 2332, 2328
Set retrievable bridge plug & wire line between Oolitic & Lovington Zones.
3. Frac down csg. w/50,000 gals. gelled water & 75,000# 20-40 Sand. Overflush w/10 BW.
4. Shut-in a minimum of 12 hours.
5. Bleed off pressure, run tbg. w/retrievable head & recover bridge plug.
6. Run tbg. & rods and put on pump.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J. F. Carnes J. F. Carnes TITLE District Production Foreman DATE 7-3-67

APPROVED BY W. R. Griest TITLE Assistant Director DATE 10/1/67

CONDITIONS OF APPROVAL, IF ANY: