

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

RECEIVED

NOV 09 '88

Form C-103
Revised 10-1-78

NO. OPERATOR RECEIVED	
DISTRIBUTION	
SANTA FE	☒
FILE	☒
U.S.O.S.	☒
LAND OFFICE	☒
OPERATOR	☒

O. C. D.
ARTESIA, OFFICE

3a. Indicate Type of Lease	
State ☒	Fee ☐
3. State Oil & Gas Lease No. E-4201	

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG SALS TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER	7. Unit Agreement Name Empire South Deep Unit
2. Name of Operator Harvey E. Yates Company	8. Name of Lease Name
3. Address of Operator P.O. Box 1933, Roswell, New Mexico 88202	9. Well No. 18
4. Location of Well UNIT LETTER F 1980 FEET FROM THE North LINE AND 1980 FEET FROM West LINE, SECTION 30 TOWNSHIP 17S RANGE 29E	10. Field and Pool, or Wildcat E. Empire Wolfcamp
11. Elevation (Show whether DF, RT, CR, etc.) 3643.4 FL	12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPER. ☐	PLUG AND ABANDONMENT ☒
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 11-2-88 Set CIBP @ 7785', w/35' cmt top, pump 100' plug 7300 - 7200 (25 sxs class "H" Neat), pump 100' plug 6000 - 5900 (25 sxs class "H" Neat), weld on 5 1/2" lift sub.
- 11-3-88 Run free point, RIH w/jet cutter, cut csg @ 3630.
- 11-4-88 Lay dwn 5 1/2" csg, RIH open ended to 3680 (50' inside of 5 1/2" csg sub) spot 25 sx plug 3680 - 3580, tag @ 3551
- 11-5-88 Pump 100' plug @ 2955 - 2850 (25 sxs class "H" Neat) pull tbq to 451', pump 100' plug @ 450 - 350 (25 sxs class "H" Neat) cutt off 8 5/8" & 13 3/8" spools, pump 10 sxs surface plug, install dry hole marker.

NOTE: Mud pumped between all plugs.

- 11-6-88 Clean location

Post ID- 2
11-18-88
P & A

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Ray T. O'Brien TITLE Production Manager/Engineer DATE 11-8-88

APPROVED BY Daniel Moore TITLE Geologist DATE 6/13/89

CONDITIONS OF APPROVAL, IF ANY: