


UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-0135
Expires: November 30, 2000



SUNDRY NOTICES AND REPORTS ON WELLS

SCANNED

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well
 Oil Well Gas Well Other **TA Well**

2. Name of Operator
EOG Resources Inc.

3a. Address **P.O. Box 2267 Midland, Texas 79702**
3b. Phone No. (include area code) **915 686 3689**

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
**1817' FNL & 1055' FEL
Sec 34, T17S, R29E**

5. Lease Serial No. **NM028775**

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.
Arco 34 Fed Com #1

9. API Well No.
30-015-31290

10. Field and Pool, or Exploratory Area
Wildcat

11. County or Parish, State
Eddy NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA


TYPE OF SUBMISSION	TYPE OF ACTION		
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal
			<input type="checkbox"/> Water Shut-Off
			<input type="checkbox"/> Well Integrity
			<input type="checkbox"/> Other _____

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

Procedure:

1. Pull 5 1/2" 17# casing from 4,000'.
2. Spot 20 sx cement plug from 4,050' to 3,925'. - TAG plug
3. Spot 30 sx cement plug from 714' to 600'. - TAG plug
4. Spot 10 sx cement plug for surface plug. - 50' CMT plug
5. Cutoff wellhead 4' below ground level. Weld on dry hole marker. Clean and level location.

Note: Hole loaded with 10 ppg mud laden fluid.



CIBP NEEDED @ 7270' + 35' CEMENT ON TOP - SEE ATTACHED

14. I hereby certify that the foregoing is true and correct.
Name (Printed/Typed) **Stan Wagner**
Stan Wagner

Title **Regulatory Analyst**
Date **10/7/02**

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by _____
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title _____
Office **SEE ATTACHED FOR CONDITIONS OF APPROVAL**