Jones Oil Company 1008 N. Guadalupé Carlsbad, New Mexico

Dear Sir:

This is to advise that we will need form C-104 and a Temperature Suprey on your Kleeman Well #1, in Section 27-18-26.

Please take care of this matter as soon as possible.

Yours very truly,

OIL CONSERVATION COMMISSION

M. L. Armstrong, Supervisor, District No. 2

MLA/jn

Jones Cil Company 1006 N. Guadalupe Garlabad, New Maxico

Dear Str:

This is to advise that we will need form 6-104 and a Temperature Survey on your Eleeman Well #1, in Section 27-18-26,

Heas take care of this matter as soon as possible.

cours very truly.

OIL NORTHWATTERS CONTRACTOR

M. L. Arretrong, Supervisor, Matrict No. 2

n;\AP