

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRII
(Other Instructions on reverse side)

NM0557370

Form approved
Bureau No. 42 R1424.

5. LEASE DISTRICT AND SERIAL NO.

10-050-58
6. IF INDIAN, AGENCY OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

RECEIVED

1. ☐ OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR
Amoco Production Company ✓

3. ADDRESS OF OPERATOR
BOX 68, HOBBS, N. M. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface
330' FSL x 1650' FEL Sec. 34 (Unit O, SW 1/4 SE 1/4)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, OR, etc.)
3626' R.D.B.

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
HARBOLO Federal

9. WELL NO.
1

10. FIELD AND FLOOD OR WILDCAT
EMPIRE Paddock

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
34-17-27 NMPM

12. COUNTY OR PARISH
EDDY

13. STATE
N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Well physically abandoned 5-16-73.

Plugged and abandoned as follows:

Spotted 25 cu cement plug from PBD-3088-2700.

(covered perfs. 3086-75)

Shot 4 1/2" casing @ 2420' 1972 & pulled.

Spotted 30 cu plug in & out of 4 1/2" stub @ 1972.

" 35 cu " " 8 5/8" shoe @ 1480'

" 10 cu " @ surface and erected P.A. marker.

all intervals filled w/ heavy mud.

Location shall be cleaned and levelled.

RECEIVED

MAY 18 1973

M. S. ORMOND, SUPERVISOR
ARTESIA, NEW MEXICOposted
7-13-73

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

AREA SUPERINTENDENT

DATE

5-16-73

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF

TITLE

DATE

APPROVED
JUL 12 1973
L. BEEKWIT
ACTING DISTRICT ENGINEERW-4- USGS-Act
1- Dir
1- So. D
1- ARCO-M
1- RIRU

*See Instructions on Reverse Side