

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO.

30-015-00741

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

BP America Production Company

3. Address of Operator

P.O. Box 1089 Eunice, NM 88231

8. Well No.

15

9. Pool name or Wildcat

Empire Abo

4. Well Location

Unit Letter G ; 2310 Feet From The N Line and 1980 Feet From The E Line

Section 02 Township 18S Range 27E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: Workover ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD: 5884' PBD: 5847' PERFS: 5762-5788' (old), 5404-5715' (new)

07.01.02: MIRUPU. NDWH. NUBOP.

07.02.02: POH w/pkr & tbq. RIH w/bit, scraper, & tbq testing tbq in hole.

07.03.02: Tag @ 5786'. POH. RIH w/RBP & pkr.

07.05.02: Set RBP @ 5442'. PU 2 jts., set pr @ 5430'. Test plug to 900# psi. Held good.
Test csg to 500#, 15 mins, held good. Unset pkr.

07.08.02: Swab well. Unset RBP & POH.

07.09.02: Perf 5405', 5464-5504', 5572-82', 5646-50', 5656-60', 5676-86', 5706-15'. RIH
w/RBP, pkr, SN, SV, & tbq. Set RBP @ 5730'. PU 1 jt. drop SV.

07.10.02: Pmp 500 gals 15% HCL NEFE followed w/8 bbls 2% KCL wtr. Wait 30 mins. Swab back
acid. Fish SV. Spot 520 gals 15% HCL NEFE followed w/10 bbls 2% KCL wtr. PU 13 jts. (OVER)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE Sr. Administrative Assistant

DATE 08.01.02

TYPE OR PRINT NAME

Kellie D. Murrish

TELEPHONE NO. 505-394-1649

(This space for State Use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

AUG 8 2002

Empire Abo Unit J-15
Subsequent Report
Workover Operations

07.10.02 cont:

Set pkr @ 5293'. Pmp 4200 gals 15% HCL NEFE dropping 250 ball sealers. Flush w/15 bbls 2% KCL wtr. Unset pkr could not go down to get RBP. POH w/tbg, SN, pkr. RIH w/retrieving head.

07.11.02:

Finish RIH. Latch on to RBP. Unset & POH. RIH & tag @ 5786'. Clean out to 5806'. POH.

07.12.02: RIH & clean out f/5806-5861'. POH. RIH w/prod. Assy. NDBOP. NUWH. Return to production. In 24 hrs pmp 0 bo, .1 bw, 199 mcf.