

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN  
(Other instr  
verse side)

Copy to SF  
Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 047633 (a)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Swearingen "A"

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Shugart

11. SEC. T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 14, T18S, R31E

12. COUNTY OR PARISH

Eddy

13. STATE

N.M.

1. OIL WELL  GAS WELL  OTHER

2. NAME OF OPERATOR

Atlantic Richfield Company

3. ADDRESS OF OPERATOR

P. O. Box 1978, Roswell, New Mexico 88201

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

1650' FNL & 2310' FWL (Unit letter F)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

This well last produced on 8/1/69 when production was 1 BOPD plus 95% water. We propose to P & A as follows:

1. Set CIBP in 7" casing at about 3140' and cap w/2 sx cement.
2. Shoot off and recover 7" casing from free point.
3. Spot these cement plugs w/9#/gal gel mud:  
30 sx in & out of 7" stub  
30 sx across 8 1/2" shoe @ 880'  
10 sx in top of well

Erect dry hole marker, clear and level location. 8" casing string will remain intact.

RECEIVED

RECEIVED

SEP 3 1971

U. S. GEOLOGICAL SURVEY  
ARTESIA NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

*A. D. Kretches*

TITLE

Dist. Drlg. Supervisor

DATE

9/1/71

(This space for Federal or State office use)

APPROVED BY  
CONDITIONS OR APPROVAL, IF ANY:

TITLE

DATE

APPROVED  
SEP - 3 1971  
*R. L. BEEKMANN*  
ACTING DISTRICT ENGINEER

\*See Instructions on Reverse Side