(REC.F.Y 517c)BY	JNI DEPARTMEN	TED STATES	<b>COD</b>		ber instr reverse	u lons on side)	Budge Expire	es Augus	1 No. 1004-013 st 31, 1985
MAY 17 1985		F LAND MANA					1		N AND SERIAL NO.
ARPHICATIO	N FOR PERMIT				1110	DACK	NM-10	193	BE OR TRIBE NAME
1ª ARTESTA, POTFICE	TON TERMIN	TO DRILL,	DEEPE	IN, OR P	LUG	BACK	-	-,	OF TRIBE RAME
DI.		DEEPEN	<b>X</b> -	PLI	UG BA	CK 🗆	7. UNIT AGE	LEEMBET	HAMB
b. TYPE OF WELL OIL WELL	GAS [		<b>*</b> ***		MULT		East Sh	ugart	Unit WF
2. NAME OF OPERATOR	ARCO Oil and G	as Company	20	NGLE XX	ZONE		8. FARM OR		
Division of .	Atlantic Richfi	eld Company	/				East Sh	ugart	Unit
8. ADDRESS OF OPERATOR						<del></del>	-	27	
P. O. Box 1710, Hobbs, New Mexico 88240							10. FIELD AND POOL, OF WILDCAT		
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*) At surface 990' FSL & 1650' FEL (Unit 0)							Shugart Yates Queen - G		
At proposed prod. so	De	(Unit 0)					11. SEC., T.,	R., M., OR	BT. F
14 histarch in Miles	as above						34 <b>-</b> 185-	-31E	
PRIVABLE IN MILES	AND DIRECTION FROM NEA	REST TOWN OR POS	T OFFICE	•			12. COUNTY	OR PARISE	13. STATE
15. DISTANCE FROM PROP	USED*		1 18 No.	OF ACRES IN			Eddy		N.M.
LOCATION TO NEAREST PROPERTY OR LEASE LINE, FT. (Also to nearest drig. unit line, if any)			20. NO.	VE ALESS IN	TEARE		OF ACRES ASSIGNED THIS WELL 4()		
18. DISTANCE FROM PROPOSED LOCATIONS			19. PRO	19. PROPOSED DEPTH 20 PG			ARY OR CABLE TOOLS		
TO NEAREST WELL, DRILLING, COMPLETED, OR APPLIED FOR, ON THIS LEASE, FT.			3	3850'			Workover Rig		
21. ELEVATIONS (Show wh	ether DF, RT, GR, etc.)					1 40.	22. APPROX	. DATE WO	ORK WILL START
3624 CTF		1					5/15		
		CAST	MC AND	4774777777					
		CASI	UNA DE	<b>CEMENTING</b>	PROGR.	AM in ho	ole		
SIZE OF HOLE	SIZE OF CASING	WEIGHT PER F		SETTING DE		AM in ho		OF CEME	NT
	SIZE OF CASING  51211 OD					25 s2	QUANTITY	OF CEME	ти
SIZE OF HOLE	I	WEIGHT PER P		SETTING DE			QUANTITY	OF CEME	NT
8" 8" Deepen in same	5½" OD	WEIGHT PER F	001	SETTING DE 3448 †	<b>СРТН</b>	25 sz	QUANTITY (		
Deepen in same Propose to run WEFE acid, set gals gelled BW.	5½" OD	epen 175' todize OH 3 gals 2% KCI	to 385	3448'  0' TD. R 850' w/40 Set BP	Run GR 000 ga @ 343	25 sz	QUANTITY  OT. Spot  l using 5  or @ 3225	200 g 00# RS	gals 15% S in 500
Deepen in same Propose to run EFE acid, set sals gelled BW. Queen perfs 329 Plush w/2% KCL	formation - 4-3/4" bit & de pkr @ 3700' & a Flush w/1700 7-3416' w/2000 wtr. Swab test	epen 175' today	oor 38563448-3. wtr. CL NEFf	3448'  0' TD. R 850' w/40 Set BP E blocked ssy & ret	Run GR 000 ga @ 343 d w/50 curn t	25 sz -CNL-LE 1s acid 0' & pk 0# RS i o produ	QUANTITY  OT. Spot  l using 5  or @ 3225  on 500 galletion.	200 g 00# RS ', aci 1s gel	gals 15% S in 500 Idize Iled BW.