

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-015-10197
Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
State Oil & Gas Lease No.
Lease Name or Unit Agreement Name Malco State
Well No. 4
Pool name or Wildcat Millman, YT-7R, East (46555)

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
Name of Operator SDX Resources, Inc.	
Address of Operator PO Box 5061, Midland, TX 79704	
Well Location Unit Letter <u>D</u> <u>660</u> Feet From The <u>North</u> Line and <u>330</u> Feet From The <u>West</u> Line Section <u>23</u> Township <u>19S</u> Range <u>28E</u> NMPM <u>Eddy</u> County	
Elevation (Show whether DF, RKB, RT, GR, etc.) <u>3412 GR</u>	

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Casing Condition:

8-5/8" @ 305' w/50 sx. TOC cald @ surf
4-1/2" @ 1210' w/75 sx. TOC calc @ 800'
Perfs: 1127-72'

Propose to P&A as follows:

Spot 25 sx plug 1172' - 822'. Tag plug. Cut & pull csg if possible. Spot 35 sx plug 355' - 255'. Spot 10 sx surf plug. Install marker & clean location.

Salt gel mud consisting of 10#
Brine W/25# of gel per bbl
must be placed between each plug

Notify OCD 24 hrs. prior to any work done

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bonnie Atwater TITLE Regulatory Tech DATE 08-25-01

TYPE OR PRINT NAME Bonnie Atwater

TELEPHONE NO. 915/685-1761

(This space for State Use)

APPROVED BY [Signature] TITLE Field Rep ID DATE 10-22-01

CONDITIONS OF APPROVAL, IF ANY

Operator SDX Resources -
 Well Malco State #4
 Unit D Section 23 Township 19 Range 28
 API # 30 - 015 - 10197

TOPS

T SALT	260
B SALT	429
Gates	736
Rivers	1124

- Salt gel mud consisting of 10# brine with 25# of gel per barrel must be placed between each plug
- Install Dry Hole Marker
- Notify OCD 24 hrs. prior to any work done

